

RECEIVED

By OCD; Dr. Oberding at 9:43 am, Mar 27, 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company : Legacy Reserves Operating, LP	Contact : Freddie Gibbs
Address : 303 W. Wall St. Ste 1300, Midland, TX 79701	Telephone No. : 432-221-6369
Facility Name : West Cap Queen Sand Unit #10	Facility Type: Central Tank Battery

Surface Owner : STATE	Mineral Owner:	API #: 30-005-01100
-----------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter O	Section 17	Township 14S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County: CHAVES
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 33.0991667 N Longitude -103.839515 W

NATURE OF RELEASE

Type of Release : Produced Water	Volume of Release : 120 bbls	Volume Recovered: -0- bbls
Source of Release : Lightning Strike	Date and Hour of Occurrence: 7/20/14	Date and Hour of Discovery: 7/21/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Hobbs NMOCD/Tomas Oberding	
By Whom? Sheldon Hitchcock Talon/LPE	Date and Hour : 7/21/14 @ 9:43 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Lightening struck the produced water tank causing a release of 120 barrels of produced water. No fluids were recovered. All fluids were contained within the berms of the battery. Talon/LPE was contacted to perform an initial site assessment and soil sampling within the impacted area.

Describe Area Affected and Cleanup Action Taken.*

Upon receipt of analytical results from the initial assessment and sampling activities, Talon/LPE drafted a remedial work plan that was subsequently approved by NMOCD. All of the work was completed in accordance with the approved work plan. Upon NMOCD approval the excavation was backfilled with caliche and contoured to match the surrounding terrain.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Hydrologist	
Printed Name: Freddie Gibbs	Approved by District Supervisor: 	
Title: Production Superintendent	Approval Date: 03/27/2015	Expiration Date: ///
E-mail Address: fgibbs@legacyp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/26/2015 Phone: 432-221-6369	///	IRP-3197

* Attach Additional Sheets If Necessary