

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: OXY	Contact: Raymond Aguilar	
Address: 1017 W Stanolind Road	Telephone No. 575-390-6312	
Facility Name: Satellite 5 Liquid Trunkline	Facility Production Trunkline	
Surface Owner: OXY	Mineral Owner:	API No.

**LOCATION OF RELEASE**

Unit Letter K	Section 4	Township 19S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude: 32.688280 Longitude: -103.1569

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 2 BBLS oil 40 BBLS water	Volume Recovered:
Source of Release: 6in fiberglass production trunkline	Date and Hour of Occurrence: 8/15/2014	Date and Hour of Discovery 8/15/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Raymond (Tony) Aguilar	Date and Hour: 8/15/2014 12:20pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD; Dr. Oberding at 9:59 am, Mar 31, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Cause of leak was by human error. A line was struck by a track hoe.

Describe Area Affected and Cleanup Action Taken.\*

Safety & Environmental Solutions, Inc. has remediated the site in accordance with NMOCD guidelines and respectfully requests closure of the regulatory file for this site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 

Printed Name: Tony Aguilar

Title: HES Specialist

E-mail Address: Raymond\_Aguilar@oxy.com

Date: 3-26-15

Phone: 575-390-6312

Hydrologist

Approved by ~~District Supervisor~~

Approval Date: 03/31/2015

Conditions of Approval:

///

Expiration Date: ///

Attached ☐

IRP-3533

\* Attach Additional Sheets If Necessary