

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Hess Corporation	Contact Donald Bull
Address 1501 McKinney Street, Houston, TX 77010	Telephone No. (713) 496-5759
Facility Name Mobil State A-1 Battery #77	Facility Type Battery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	2	20S	36E					Lea County, NM

Latitude N 32.60601° Longitude W 103.31889°

NATURE OF RELEASE

Type of Release Unknown, historical	Volume of Release Unknown, historical	Volume Recovered Unknown, historical
Source of Release Unknown, historical	Date and Hour of Occurrence Unknown, historical	Date and Hour of Discovery Unknown, historical
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? n/a	
By Whom? n/a	Date and Hour n/a	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



RECEIVED
By OCD; Dr. Oberding at 12:18 pm, Apr 01, 2015

If a Watercourse was Impacted, Describe Fully.*
n/a

Describe Cause of Problem and Remedial Action Taken.*
This is a former tank battery that has been abandoned. The hydrocarbon impact is historical in nature. Remediation was completed.

Describe Area Affected and Cleanup Action Taken.*
The tank battery site was assessed and delineated. A remediation plan was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 08/08/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Donald Bull	Approved by Hydrologist 	Specialist: 
Title: Senior Specialist	Approval Date: 04/01/2015	Expiration Date: 
E-mail Address: dbull@hess.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/26/15 Phone: (713) 496-5759	///	1RP-3282

* Attach Additional Sheets If Necessary