

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	East Eumont Satellite #3 Battery	Facility Type	Battery
Surface Owner	State/Oxy	Mineral Owner	
		API No.	30-025-05592

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	10	19S	37E					Lea

Latitude N 32.67388° Longitude W 103.24570°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	9 bbls	Volume Recovered	0 bbls
Source of Release	Bullet hole in 4" poly production line	Date and Hour of Occurrence	03/22/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding- NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	03/23/2015 @ 11:18 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 11:45 am, Apr 01, 2015


Describe Cause of Problem and Remedial Action Taken.*

A bullet hole in a 4" poly production line caused 9 bbls of oil to leak onto the ground. No fluids were recovered and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 40' x 100' off location in the pasture. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=cjones88@yahoo.com, c=US Date: 2015.03.31 20:53:42 -05'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones	Hydrologist Approved by District Supervisor	
Title: HES Specialist	Approval Date: 04/01/2015	Expiration Date: 07/01/2015
E-mail Address: Christopher.jones@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3589 192463
Date: 3/31/15	Phone: (575) 628-4121	

* Attach Additional Sheets If Necessary

nTO1509142499

pTO1509142712