

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Cascade 29 Fed 3	Facility Type	production

Surface Owner	Mineral Owner	API No.	30-025-41241
---------------	---------------	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	26S	32E	330	N	2310	E	Lea

Latitude 32.064165 Longitude -103.652791

### NATURE OF RELEASE

Type of Release	produced water	Volume of Release	60 bbls	Volume Recovered	0
Source of Release	flowline	Date and Hour of Occurrence	3/29/2015	Date and Hour of Discovery	3/29/2015
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Doc Oberding/ Sol Hughes		
By Whom?	Christine Alderman	Date and Hour	3/30/2015 3:53 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD; Dr. Oberding at 9:37 am, Apr 03, 2015

Describe Cause of Problem and Remedial Action Taken.\*

It appeared that a backhoe (not hired by Cimarex) had driven through the pasture and ran over our line causing it to rupture.

Describe Area Affected and Cleanup Action Taken.\*

The fluids impacted an area approximately 75' x 60' in pasture area. An arch study has been requested and a consulting company will be onsite to develop workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christine Alderman	Hydrologist	Approved by <del>Environmental Specialist</del> <i>[Signature]</i> PhD
Title: ESH Supervisor	Approval Date: 04/03/2015	Expiration Date: 07/04/2015
E-mail Address: calderman@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/2/2015 Phone: 432-853-7059	Site samples required. Delineate and remediate area as per NMOCD guides.	IRP-3590 215099

\* Attach Additional Sheets If Necessary

nTO1509335039

pTO1509335241