

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Mallon 33 Fed 4	Facility Type	production

Surface Owner	Mineral Owner	API No.	30-025-34114
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	33	19S	34E	1980	N	560	E	Lea

Latitude 32.61858 Longitude -103.55856

NATURE OF RELEASE

Type of Release	oil	Volume of Release	255 bbls	Volume Recovered	25 bbls
Source of Release	Steel tank	Date and Hour of Occurrence	4/2/2015 9:00am	Date and Hour of Discovery	4/2/2015 9:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Doc Oberding/Sol Hughes		
By Whom?	Christine Alderman	Date and Hour	4/2/2015 1:50pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By OCD; Dr. Oberding at 11:49 am, Apr 06, 2015

Describe Cause of Problem and Remedial Action Taken.*
A corrosion hole developed in the bottom of the steel oil tank.

Describe Area Affected and Cleanup Action Taken.*
The fluids were mainly contained inside an unlined berm. A small amount got out onto the location pad. The area will be delineated and a work plan developed for clean up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Hydrologist Approved by <i>[Signature]</i> Environmental Specialist	<i>[Signature]</i> P.D.O.
Title: ESH Supervisor	Approval Date: 04/06/2015	Expiration Date: 07/06/2015
E-mail Address: calderman@cimarex.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3592 162683
Date: 4/6/2015 Phone: 432-853-7059		

* Attach Additional Sheets If Necessary

nTO1509642813

pTO1509643006