

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBSOCD

APR 09 2015

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Horse shoe operating	Contact	William K Dean
Address		Telephone No.	575-631-5010
Facility Name	N.M. St. G #15	Facility Type	Battery
Surface Owner	SLO	Mineral Owner	
		API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	26	215	36E	N/A	N/A	N/A	N/A	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	50 BBL	Volume Recovered	47 BBL
Source of Release	hole in Tank	Date and Hour of Occurrence		Date and Hour of Discovery	N/A
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	7.5.2014		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

None

RECEIVED

By OCD; Dr. Oberding at 9:49 am, Apr 10, 2015

Describe Cause of Problem and Remedial Action Taken.*

oil Tank ran over spilling 50 BBL of Crude oil into Dyke. Picked up 47 BBL
crew went into Dyke and removed contaminated soil and haul to land farm
bring in clean soil for Battery and Firewall

Describe Area Affected and Cleanup Action Taken.*

Inside Dyke at Battery was affected. went inside Dyke excavated
down about 1' took Adeld samples clean on chlorides take
samples to lab.

I hereby certify the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: William K Dean		OIL CONSERVATION DIVISION	
Printed Name: WILLIAM K DEAN		Hydrologist	
Title: LEASE OPERATOR		Approved by Environmental Specialist: [Signature]	
E-mail Address: DEANS PUMPING @ AOL.COM		Approval Date: 04/10/2015	Expiration Date: 07/10/2015
Date: 3/20/15	Phone: 575-631-5010	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides. Provide photographic documentation of remediation.	Attached <input type="checkbox"/> IRP-3598 225243

* Attach Additional Sheets If Necessary

5011

FTOI510035714

nTOI510035819

pTOI510035973