

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company RGS TRUCKING	Contact Ruben Perez
Address 1011 E. Sanger Hobbs NM 88240	Telephone No. 432 561 8804
Facility Name RGS TRUCKING	Facility Type haul trucks
Surface Owner <del>Fasken Oil &amp; Ranch</del> New Mexico State Land	Mineral Owner Fasken Oil & Ranch
API No. 30-025-40680 Laguna #16 State 2H	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------	----------	-------	---------------	------------------	---------------	----------------	-------------

Latitude 32.56715850 Longitude -103.76599950

#### NATURE OF RELEASE

Type of Release produced water	Volume of Release 1400 BBLs	Volume Recovered 0 (zero)
Source of Release RGS haul truck released produced water on site	Date and Hour of Occurrence <del>1/17/2015</del> morning 01/20/2015	Date and Hour of Discovery <del>1/17/2015</del> morning 01/20/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? No notice provided	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. No waters of the US affected.	

If a Watercourse was Impacted, Describe Fully.\*  
Upon review of case file, OCD corrected the dates as noted.

No waters of the US affected


Describe Cause of Problem and Remedial Action Taken.\*

20  
Based on OCD document dated Jan 26 2015, Mr Pedro Prado, driving the RGS truck, admitted to dumping several loads of produced water on Fasken property from the R360 Surface Waste Management Facility. From OCD approx. 14 separate unauthorized discharges occurred.

Describe Area Affected and Cleanup Action Taken.\*

Approx 250 ft around the white pin flags is the area of concern. Remediation will include length, width and depth discovery of contamination including testing for TPH, chlorides, RCRA metals and BTEX. Detailed remediation plan will be completed soon and sent to OCD for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature 		OIL CONSERVATION DIVISION	
Printed Name: Richard Costa		Hydrologist Approved by <del>Environmental Specialist</del>	
Title: Environmental Engineer		Approval Date: 01/29/2015	Expiration Date: <del>03/29/2015</del> 04
E-mail Address: rcosta@onesourceindusrrial.com		Conditions of Approval: Site samples required. Delineate and remediate area as per	
Date: Jan 28 2015 Phone: 432 258 4444		Attached <input type="checkbox"/> IRP-3518	

NMOCD guides. Submit final  
C-141 by 03/29/2015.

pTO1502939121  
nTO1502938832