

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff	
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3143	
Facility Name: VGEU West Battery	Facility Type: Battery	
Surface Owner: NMOCD	Mineral Owner NMOCD	API No. 3002521012

LOCATION OF RELEASE

Unit Letter D	Section 32	Township 17S	Range 35E	Feet from the 760	North/South Line North	Feet from the 660	East/West Line West	County LEA
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude **32.7967056673181** Longitude - **103.486328516973**

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 70 BBLS	Volume Recovered: 40 BBLS
Source of Release: Water Tank	Date and Hour of Occurrence 03/26/14 1:00 am	Date and Hour of Discovery 03/26/14 4:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Spencer Cluff	Date and Hour: 03/26/2014 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED

By OCD; Dr. Oberding at 9:16 am, Apr 13, 2015

Describe Cause of Problem and Remedial Action Taken.* There was a power outage caused by lightening. The automatic SWD valve could not function without power. The valve had to be manually opened.

Describe Area Affected and Cleanup Action Taken.*
Pasture area was 285 ft. X 225 ft. and will be remediated according to NMOCD requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Spencer Cluff		Approved by Hydrologist	
Title: LEAD HSE		Approval Date: 04/13/2015 Expiration Date: ///	
E-mail Address: spencer.a.cluff@conocophillips.com		Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	
Date: 03/27/2014 Phone: 575-391-3143		Attached <input type="checkbox"/> 1RP-3603 217817	

* Attach Additional Sheets If Necessary

nTO1510334242

pTO1510334480