

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Bruce Baker
Address	2350 W. Marland Blvd, Hobbs, NM 88240	Telephone No.	(432) 631-6982
Facility Name	NEDU #157	Facility Type	Fiberglass line

Surface Owner	Farm and Ranch Limited	Mineral Owner		API No.	30-025-40696
---------------	------------------------	---------------	--	---------	--------------

BLM

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	3	21S	37E	1830	FNL	1744	FEL	Lea

Latitude N32.8117 Longitude W104.0582

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	225 bbls	Volume Recovered	190 bbls
Source of Release	2" in fiberglass line	Date and Hour of Occurrence	4/3/15	Date and Hour of Discovery	4/3/15
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Dr. Tomas Oberding		
By Whom?	Bruce Baker	Date and Hour	4/3/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

By OCD; Dr. Oberding at 1:47 pm, Apr 14, 2015

If a Watercourse was Impacted, Describe Fully.*	
---	--

Describe Cause of Problem and Remedial Action Taken.* A fiberglass line cracked releasing fluid over the pasture. The well was shut in and line repaired. Vacuum trucks were dispatched to pick-up standing fluid.
--

Describe Area Affected and Cleanup Action Taken.* The release area covered 6,853 sq ft of the pasture to the west of the #157 lease pad. A path forward will be submitted to NMOCD after delineation efforts.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Hydrologist	Approved by Environmental Specialist: <i>[Signature]</i> P.D.O.
Title: Environmental Technician	Approval Date: 04/14/2015	Expiration Date: 07/14/2015
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/>
Date: 4/13/15 Phone: (432) 631-6982	Provide photographic documentaiton of remediation.	1RP-3607 873

* Attach Additional Sheets If Necessary

nTO1510449969

pTO1510452101