

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	(432) 686-3667
Facility Name	Vaca 24 Federal Com #3H	Facility Type	Oil Well
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-40530

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	24	25S	33E	1855	South	1213	West	Lea

Latitude 32.113754 Longitude -103.530836

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	unknown	Volume Recovered	30 BBLs
Source of Release	6 inch poly line rupture	Date and Hour of Occurrence	4/13/2015	Date and Hour of Discovery	4/13/2015 at approximately 12:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 3:41 pm, Apr 15, 2015

Describe Cause of Problem and Remedial Action Taken.*

A six inch poly line north of the Vaca 24 Federal Com #3H had broken apart at a seam due to over pressure. The line was repaired immediately upon discovery.

Describe Area Affected and Cleanup Action Taken.*

Approximately 30 BBLs of produced water were vacuumed up upon discovery. Assessment and excavation of the soil in the area will take place in the near future.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bernard Boucisch</i> FOR EOG RESOURCES INC.		OIL CONSERVATION DIVISION	
Printed Name: BERNARD BOUCISCH		Hydrologist	Approved by Environmental Specialist: <i>[Signature]</i> PLO
Title: Sr. PROJECT MANAGER / CRA	Approval Date: 04/15/2015	Expiration Date: 07/15/2015	
E-mail Address: BBoucisch@CRAworld.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides. Provide geotagged photographs documenting the remediation.		Attached <input type="checkbox"/> 1RP-3610 7377
Date: 4/15/15	Phone: 505-884-0672		

* Attach Additional Sheets If Necessary

nTO1510556739

pTO1510556875