

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	CE Lamunyon #41 CTB	Facility Type	Battery
Surface Owner	George Weir	Mineral Owner	
		API No.	30-025-22609

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	21	23S	37E					Lea County, NM

**RECEIVED**

Latitude N 32.28411°

Longitude W 103.16349°

By OCD; Dr. Oberding at 2:18 pm, Apr 22, 2015

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Pump failure caused the tanks to spill over	Date and Hour of Occurrence	04/29/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/29/2014 @ 1:08 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**INFORMATION ONLY**

Describe Cause of Problem and Remedial Action Taken.\*

Accepted for record only.

Pump failure caused the tanks to spill 10 bbls of produced water onto the ground. No fluids were recovered and the pump was repaired/reset.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 300' x 150' on location. Remediation was completed in accordance with a remediation plan approved by Tomas Oberding of NMOCD via email on 10/15/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christopher Jones		Approved by Environmental Specialist:	
Title: HES Specialist	Approval Date: 04/22/2015	Expiration Date: ///	
E-mail Address: Christopher_Jones@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	Phone: (575) 628-4121	Requires signature.	1RP-3341

\* Attach Additional Sheets If Necessary