

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: QPBSSU 6-1	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-025-29623
--------------------	--------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter M	Section 24	Township 18S	Range 32E	Feet from the 660'	North/South Line South	Feet from the 660'	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.727427 Longitude -103.726236

#### NATURE OF RELEASE

Type of Release: Oil Mist	Volume of Release: 5 bbls	Volume Recovered: N/A
Source of Release: Poly flow line	Date and Hour of Occurrence 4-21-15 4:00 pm	Date and Hour of Discovery 4-21-15 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Soloman Hughes	
By Whom? Zack Thomas	Date and Hour 4-22-15 3:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**

By OCD; Dr. Oberding at 2:09 pm, Apr 23, 2015

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Equipment failure- Poly flow line over pressured and popped. Pumping unit was shut off; also tubing and casing valves were shut to stop the release.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- The ruptured flow line misted the pasture to the Northwest of pad an estimated 150 yards by 50 yards. Cleanup efforts (to be determined) will be in conjunction with NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Thomas	Hydrologist	Approved by Environmental Specialist: 
Title: Environmental Rep.	Approval Date: 04/23/2015	Expiration Date: 07/23/2015
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides. Provide geotagged photographs of remediation.	Attached <input type="checkbox"/> IRP_3617 14744
Date: 4-23-15 Phone: 575-602-2188	nTO1511353679 pTO1511353880	

\* Attach Additional Sheets If Necessary