RECEIVED

By OCD; Dr. Oberding at 11:11 am, Apr 24, 2015

District I

1625 N. French Dr., Hobbs, NM 88240

District II
811 S. First St., Artesia, NM 88210

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

						OPERA'	ГOR		- ☐ Initi	al Report	⊠ F	inal Repor
Name of Cor				Contact Christopher Jones								
	502 W. C	and the second		Telephone No. (575) 628-4121								
Facility Nam	ne Man	attery		Facility Type Tank Battery								
Surface Own	ner BLN	A	Mineral C)wner	API No.							
				LOCA	TIO	N OF RE	LEASE					
Unit Letter	Unit Letter Section Township Range Feet from the No.				North	th/South Line Feet from the Eas			/West Line County			
С	28	22S	37E			Lea County, NM					, NM	
			1	Latitude N 32.3	6877°	Longitu	de <u>W 103.1698:</u>	<u>5°</u>				
Type of Release Oil and Produced water Volume of Release Volume Recovered												
Type of Releas	se Oil ar		Volume of Release Volume R				ecovered					
Source of Rele	ease Wat	d Date and Hour of Occurrence Date and				Hour of Discovery						
the oil tanks to		03/17/2014										
Was Immediat	te Notice G	If YES, To Whom? Geoffrey Leking, NMOCD and Jennifer VanCuren, BLM										
	Kathy Pur	Date and Hour 03/17/2014 @ 3:08 pm										
Was a Waterco	ourse Reac	No		If YES, Volume Impacting the Watercourse.								
IC - Water	The same of the sa											
If a Watercourse was Impacted, Describe Fully.*												
APPROVED												
By OCD; Dr. Oberding at 11:11 am, Apr 24, 2015												
Describe Cause of Problem and Remedial Action Taken.*												
The water dump on the separator malfunctioned and caused the oil tanks to overflow spilling 40 bbls of oil and produced water onto the ground. No fluids were recovered and the water dump issue was resolved.												
Describe Area	Affected a	nd Cleanup A	ction Tak	en.*								
					•		- 100 March 100	•		• •	_	
The affected area is approximately 8' x 80' on location. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 10/22/2014.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations. Chris Digitally signed by Chris Jones DN: cn=Chris Jones o, ou. OIL CONSERVATION DIVISION												
				OIL CONSERVATION DIVISION								
Signature: Jo	nes_	0'		Hydro								
Printed Name:	Christop		A	Approved by Environmental Specialist:								
Title: HES S	Specialist			A	Approval Date	e: 04/24/2015	E	Expiration I	Date:	1		
E-mail Address: Christopher Jones@oxy.com						Conditions of Approval:				Attached		
Date: (575) (29 4121						///			===			
Date: Attach Addition	onal Sheet	s If Necessa	Phone:	(575) 628-4121						1RP-334	4	