

**RECEIVED**

By OCD; Dr. Oberding at 8:55 am, Aug 21, 2015

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Hess Corporation	Contact	Donald Bull
Address	1501 McKinney Street, Houston, TX 77010	Telephone No.	(713) 496-5759
Facility Name	Texaco State E Battery #79	Facility Type	Battery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	I	20S	36E					Lea County, NM

Latitude N 32.59872°

Longitude W 103.31210°

**APPROVED**

By OCD; Dr. Oberding at 8:55 am, Aug 21, 2015

**NATURE OF RELEASE**

Type of Release	Unknown, historical	Volume of Release	Unknown, historical	Volume Recovered	Unknown, historical
Source of Release	Unknown, historical	Date and Hour of Occurrence	Unknown, historical	Date and Hour of Discovery	Unknown, historical
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	n/a		
By Whom?	n/a	Date and Hour	n/a		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

n/a

Describe Cause of Problem and Remedial Action Taken.\*

This is a former tank battery that has been abandoned. The hydrocarbon impact is historical in nature. Remediation was completed.


Describe Area Affected and Cleanup Action Taken.\*

The tank battery site was assessed and delineated. A remediation plan was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 08/08/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:



Printed Name: Donald Bull

Title: Senior Specialist

E-mail Address: dbull@hess.com

Date: 3/26/15

Phone: (713) 496-5759

Hydrologist

Approved by Environmental Specialist:

Approval Date: 08/21/2015

Conditions of Approval:

Expiration Date:

Attached ☐

1RP-3281

\* Attach Additional Sheets If Necessary

pTO1424040039