

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By OCD; Dr. Oberding at 9:36 am, Oct 28, 2015  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141  
Revised August 8, 2011

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: Chevron USA, Inc.	Contact: Jeff Euhus
Address: Highway 128 PO Box 30, Andrews, TX 79714	Telephone No.: 713-372-9983
Facility Name: Dollarhide Field Office	Facility Type: Oil field
Surface Owner: Chevron USA, Inc.	Mineral Owner:
	API No.

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	009	025S	038E					Lea

Latitude 32.140626 Longitude -103.064844

#### NATURE OF RELEASE

Type of Release: Historical release	Volume of Release: Unknown	Volume Recovered: Unknown
Source of Release: drilling/produced water from historical unlined production pits and evaporation ponds	Date and Hour of Occurrence: N/A, Historical	Date and Hour of Discovery: N/A, Historical
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



**APPROVED**

By OCD; Dr. Oberding at 9:36 am, Oct 28, 2015

Describe Cause of Problem and Remedial Action Taken.\* Unlined production pits and evaporation ponds were historically used within the Dollarhide Field Unit in Texas

Describe Area Affected and Cleanup Action Taken.\*  
Land in the vicinity is used for cattle grazing, and oil/gas production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy Sierra	Approved by:  Hydrologist	Approved by:  <del>Environmental Specialist</del>
Title: Area Manager - Upstream Business Unit/MCA Chevron Environmental Management Company	Approval Date: 10/28/2015	Expiration Date: ///
E-mail Address: AmySierra@chevron.com	Conditions of Approval: Provide OCD with updates, and plans for remediation.	Attached <input type="checkbox"/> IRP-3944
Date: <u>10/28/15</u> Phone: 713-372-1045		

\* Attach Additional Sheets If Necessary

fTO1530147165  
nTO1530147335  
pTO1530147549