

**3R – 470**

**C-141**

**06 / 19 / 2015**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: XTO Energy, Inc.	Contact: Kurt Hoekstra	
Address: 382 Road 3100, Aztec, New Mexico 87410	Telephone No.: (505) 333-3100	
Facility Name: Sullivan Gas Com D # 1E	Facility Type: Gas Well (Basin Dakota)	
Surface Owner: Private	Mineral Owner	API No.: 30-045-24083

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	26	29N	11W	1475	FNL	1500	FWL	San Juan

**Latitude 36.70002 Longitude -107.96414**

**NATURE OF RELEASE**

Type of Release: Condensate	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Fiberglass line from the separator to the production tank.	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 6-5-2015 10:06 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* On 6-1-2015 while replacing the fiberglass line from the separator to the production tank, dark soil with a hydrocarbon order was discovered. On 6-2-2015 a grab sample was collected six feet below the surface under a pipe union that could be the source of the impacted soil. The sample result was obtained on 6-5-2015, these results were above the standards for the Remediation of Leaks, Spills and Releases at 5400 ppm TPH USEPA Method 8015 and Total BTEX of 521.2 ppm USEPA Method 8021. The site was then ranked according to the NMOCD Guidelines for the Remediation of Leaks, Spills and Releases. The site was ranked a 20 due to an estimated depth to groundwater of less than 50 feet, distance to a water well greater than 1000 feet, and distance to surface water greater than 1000 feet. This set the closure standard to 100 ppm TPH, 10 ppm benzene, and 50 ppm total BTEX.

Describe Area Affected and Cleanup Action Taken.\*Based on the sample results of 5400 ppm TPH USEPA Method 8015 and Total BTEX of 521.2 ppm USEPA Method 8021, a release has been confirmed at this location. Remediation activities are in progress.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kurt Hoekstra</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kurt Hoekstra		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Coordinator	Approval Date: 7/6/15	Expiration Date:	
E-mail Address: Kurt_Hoekstra@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 6-19-2015 Phone: 505-333-3100	Submit Remediation plan		

\* Attach Additional Sheets If Necessary

#NCS 1518952648

①