

Victory Energy Services, LLC

PO Box 1148

Eunice NM 88231

575-394-0219

#### Procedure of Cleanup on State X Location

Cleaning up the State X location consisted of 3 weeks of cleanup. Started at the tanks. Gang broke up approximately 6" of hard oil packed dirt. Got down and dug an additional 6" to good clean soil and started the clean around the heater and circulating pump and removed old lines and dug out approximately 6" of oily hard packed dirt. Dug an additional 6" to good clean soil and got samples and took to Cardianal Lab for testing. Samples came back good so we went back and filled in the areas with good clean soil. Built burms around tank and heater treater.

Josh Ruth