

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Breitburn Operating LP	Contact Buck Pollister
Address 1111 Bagby Street, Suite 1600 Houston TX 77002	Telephone No. 575-741-0153
Facility Name Libby Minerals 1931 No. 271	Facility Type CO2 Well

Surface Owner: Yesterday Valley Ranch, Inc. (Mary Libby Campbell)	Mineral Owner Libby Minerals LLC Contact: Mary Libby Campbell	API No. 30-021-20581
---	--	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 27	Township 19N	Range 31E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line East	County Harding
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-------------------

Latitude 35.8463631 Longitude -103.6316376 NAD83

NATURE OF RELEASE

Type of Release Waste Water	Volume of Release: Est. 10 bbls	Volume Recovered: Est. 10 bbls
Source of Release Water Storage Tank Overflow	Date and Hour of Occurrence 03/2017	Date and Hour of Discovery 03/2017
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water hauler was delayed and tank overflowed. All water remained within containment area.

Describe Area Affected and Cleanup Action Taken.*

Water has been vacuumed from containment area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Shelly Doescher	Approval Date: 19Apr17	Expiration Date:
Title: Agent	Conditions of Approval:	
E-mail Address: shelly_doescher@yahoo.com	Attached <input type="checkbox"/>	
Date: 04/11/2017	Phone: 505-320-5682	

* Attach Additional Sheets If Necessary