From:	Madison, Randy L.
To:	Bayliss, Randolph, EMNRD
Subject:	Emailing: C141 Spill Form Report NM E-19 Main Line 6-27-17 1498653487872, VPR "E" 19 Water Analysis
Date:	Monday, July 3, 2017 8:41:51 AM
Attachments:	C141 Spill Form Report NM E-19 Main Line 6-27-17 1498653487872.doc VPR "E" 19 Water Analysis.pdf

---

Mr. Bayliss
Here is the C-141 form for the spill I reported last week. The leak has been repaired and no remediation need on the release. I have attached a copy of the water analysis closed to the leak. This is a representation of the water in the line. Produced water quality data from the well associated with or representative of the spill is attached. ARP Production Co., LLC (ARP) has found that in the Raton Basin CBM field, soil confirmation sampling no longer adds useful data on low volume acute releases of CBM produced water, as land uses and the environment are not impacted. Long term or negative effects to soil chemistry from low volume acute CBM produced water spills are generally surficial and benign, in that the water does not contain crude oil or liquid hydrocarbons; the TDS is significantly less than 10,000 mg/L; it is suitable for livestock watering, wildlife and in many cases surface discharge. Mixed with other water it is suitable for irrigation without impact. When requested by the agency or Vermejo Park Ranch ARP has and will collect soil samples. ARP requests closure of this incident based on this statement and attached water quality data.
Randy

Randy L. Madison
EHS Specialist
Atlas | Titan
309 Silver St
Raton, NM 87740
Office 575-445-6706
Cell 575-420-1120
Fax 575-445-6788
E-Mail rmadison@atlasenergy.com

Your message is ready to be sent with the following file or link attachments:

C141 Spill Form Report NM E-19 Main Line 6-27-17 1498653487872
VPR 'E' 19 Water Analysis

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.