

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ARP Production Company, LLC	Contact	Randy L. Madison
Address	309 Silver St., Raton, NM 87740	Telephone No.	Office 575-445-6706 Cell 575-420-1120
Facility Name:	6" E-Pod Main Line	Facility Type:	Flow Line

Surface Owner:	Vermejo Park Ranch	Mineral Owner:	APR Production Company, LLC	API No.
----------------	--------------------	----------------	-----------------------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	6	31N	19E					Colfax

Latitude_N 36.8981 Longitude_W 104.9828

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 12 Barrels	Volume Recovered: 0
Source of Release: 6" Main Flow Line	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 7/10/17@1000 hrs.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randolph Bayliss	
By Whom? Randy Madison, EHS Specialist	Date and Hour: 7/10/17@1015 hrs.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

2" valve on a vent did not get closed all the way. This resulted in a small spray of water releasing 12 barrels of produced water on to the ground. The valve was closed and a bull plug installed.

Describe Area Affected and Cleanup Action Taken.*

The produced water remained in the ditch alongside the road. The water that did not evaporate dissipated into the ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: 	
Title: EHS Specialist		Randolph Bayliss, Hydrologist	
E-mail Address: rmadison@atlasenergy.com		Approval Date: 02 Oct 17	Expiration Date: na
Date: 7/13/17 Phone: 575-445-6706		Conditions of Approval: none	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary