

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: ARP Production Company, LLC	Contact: Randy L. Madison	
Address: 309 Silver St., Raton, NM 87740	Telephone No. : 575-445-6706	
Facility Name: VPR A-117	Facility Type: Gas Well	
Surface Owner: Vermejo Park Ranch	Mineral Owner: ARP Production Company, LLC	API No.: 30-007-20421

LOCATION OF RELEASE

Unit Letter F	Section 24	Township 31N	Range 19E	Feet from the 1722	North/South Line North	Feet from the 2190	East/West Line West	County Colfax
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude: N 36.909671 Longitude: W 104.873915 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 18 Barrels	Volume Recovered: 0 Barrels
Source of Release: Frozen Check Valve @ Wellhead	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 2/7/2018 @ 0949
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Griswall and Randolph Bayliss	
By Whom? Randy Madison	Date and Hour: 2-7-18 @ 1015	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

2" valve froze and split do to cold weather. The valve was replaced. Heat trace was rerouted to have more contact with the valve.

Describe Area Affected and Cleanup Action Taken.*

This was produced water. The water froze. No cleanup will be done. The area will be monitored for vegetation kill. See attached water analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: 	
Title: HSE Specialist	Approval Date: 13Feb18	Expiration Date: n.a.	
E-mail Address: rmadison@atlasenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 2-12-18	Phone: 575-445-6706	Photos before and after PW melts	

* Attach Additional Sheets If Necessary