

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NDHR1912143128
District RP	IRP-5446
Facility ID	fDHR1912142203
Application ID	pDHR1912142630

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380
Contact Name Kyle Littrell	Contact Telephone 432-221-7331
Contact email Kyle_Littrell@xtoenergy.com	Incident # (assigned by OCD) NDHR1912143128
Contact mailing address 522 W. Mermod, Carlsbad, NM 88220	

Location of Release Source

Latitude 32.56058 Longitude -103.31849
(NAD 83 in decimal degrees to 5 decimal places)

Site Name EMSU B Tank Battery	Site Type Bulk Storage and Separation Facility
Date Release Discovered 4/4/2019	API# (if applicable) N/A

Unit Letter	Section	Township	Range	County
A	23	20S	36E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: BLM)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 7.89	Volume Recovered (bbls) 7.75
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release


A 4 inch flange separated from a nipple on trunkline coming from freewater knockout and tester to the heater treater. A contract crew was onsite performing work when fluids were released to the well pad. The crew built a berm to contain the release. A vacuum truck recovered all free fluids. Additional third party resources have been retained to assist with remediation.

Incident ID	NDHR1912143128
District RP	1RP-5446
Facility ID	fDHR1912142203
Application ID	pDHR1912142630

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? N/A
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? N/A	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: N/A	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Amy C. Ruth</u> Signature:  email: <u>Amy_Ruth@xtoenergy.com</u>	Title: <u>SH&E Coordinator</u> Date: <u>4/16/2019</u> Telephone: <u>575-689-3380</u>
<u>OCD Only</u> Received by: <u>Dylan Rose-Coss</u> Date: <u>05/01/2019</u>	

Location:	EMSU B Tank Battery	
Spill Date:	4/4/2019	
OR		
Approximate Area=	32	ft ²
Average Saturation (or depth) of Spill=	10.00	inches

Approximate Oil %	100	
Average Porosity Factor=	0.03	
Approximate Volume Recovered=	7.75	bbls

VOLUME OF LEAK		
Total Oil=	7.89	barrels
Total Produced Water=	0	barrels

VOLUME RECOVERED		
Total Oil=	7.75	barrels
Total Produced Water=	0	barrels