	ENACLI (1205 /20 225 24524)	
Location: EMSU #306 (30-025-04604)		
Spill Date:	4/13/2019	
Length of Spill=	53.00	feet
Width of Spill=	40.00	feet
Saturation (or de	epth) of Spill= 2.00	inches
Approximate Oil	% 4	
Porosity Factor=	0.03	
Volume Recover	ed= 5.00	bbls

VOLUME OF LEA	AK	
Total Oil=	0.28	barrels
Total Produced Water=	6.61	barrels
VOLUME RECOVE	RED	
Total Oil=	0.2	barrels
Total Produced Water=	4.8	barrels
Length of Spill=	145.00	feet
		licet
Width of Spill=	1.50	feet
	1.50 1.00	
Width of Spill=		feet
Width of Spill= Saturation (or depth) of Spill=	1.00	feet

VOLUME OF LEAK				
Total Oil=	0.02	barrels		
Total Produced Water=	0.46	barrels		