

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NDHR1918658476
District RP	IRP-5606
Facility ID	fDHR1918658363
Application ID	pDHR1918658098

Release Notification

Responsible Party

Responsible Party Goodnight Midstream Permian, LLC	OGRID 372311 DHR7/5/19
Contact Name Ralph Tijerina	Contact Telephone 214-587-4964
Contact email rtijerina@goodnightmidstream.com	Incident # (assigned by OCD)
Contact mailing address 5910 N Central Expy, Dallas, TX 75206	

Location of Release Source

Latitude 32.472598 Longitude -103.207210
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Piper SWD	Site Type SWD
Date Release Discovered 6/24/2019	API# (if applicable)

Unit Letter	Section	Township	Range	County
M	18	21S	37E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 400	Volume Recovered (bbls) 355
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release – A storage tank caught fire causing the release. Containment held most of the release; approximately 45 bbls left containment.

State of New Mexico
Oil Conservation Division

Incident ID	NDHR1918658476
District RP	1RP-5606
Facility ID	fDHR1918658363
Application ID	pDHR1918658098

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Greater than 25 bbls
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Daniel Dominguez with Etech Environmental notified Mr. Rickman at the OCD via email on 6/25/2019.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Ralph Tijerina</u>	Title: <u>Director - EHS</u>
Signature: <u>Ralph Tijerina</u>	Date: <u>6/28/19</u>
email: <u>rtijerina@goatwhistmisdream.com</u>	Telephone: <u>214447001</u>
<u>OCD Only</u>	
Received by: <u>Dylan Rose-Coss</u>	Date: <u>07/05/2019</u>