District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NDHR1918660089
District RP	1RP-5607
Facility ID	
Application ID	pDHR1918659716

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380
Contact Name Kyle Littrell	Contact Telephone 432-221-7331
Contact email Kyle_Littrell@xtoenergy.com	Incident # (assigned by OCD) NDHR1918660089
Contact mailing address 522 W. Mermod, Carlsbad, NM	[88220

Location of Release Source

Longitude _

-103.609785°

Latitude 32.255141°

Site Name Mis Amigos Battery	Site Type Bulk Storage and Separation Facility
Date Release Discovered 6/18/2019	API# (if applicable) 30-025-40590

Unit Letter	Section	Township	Range	County
0	31	238	33E	Lea

Surface Owner: X State Federal Tribal Private (Name: _______ New Mexico

Nature and Volume of Release

X Crude Oil	Volume Released (bbls) 0.05 bbl	Volume Recovered (bbls) 0
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
🗌 Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Fire: Flare scrubber loaded up and caused a mist of oil to escape the flare and ignite a mesquite bush. The lease operator suppressed the fire with his fire extinguisher. No injuries were reported. Additional third party resources have been retained to assist with remediation.

Form C-141

Page 2

N/A

State of New Mexico Oil Conservation Division

Incident ID	NDHR1918660089
District RP	1RP-5607
Facility ID	
Application ID	pDHR1918659716

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release? An unauthorized release of a volume that results in a fire or is the result of a fire	
Yes 🗌 No		
If YES, was immediate n Notice provided by Amy	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Ruth to EMNRD-OCD_District1spills and Ryan Mann (SLO) on 6/19/2019 by email	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \blacksquare The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Anty C. Ruth Signature: Any Ruth@xtoenergy.com	Title: SH&E Coordinator Date: 7/1/2019 Telephone: 575-689-3380
OCD Only	
Received by:	Date:

Form C-141 State of New Mexico Incident ID **Oil Conservation Division** Page 4 District RP Facility ID Application ID I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Title: SH&E Coordinator Printed Name: Amy C. Ruth Date: 7/1/2019 Signature: Telephone: 575-689-3380 Amy_Ruth@xtoenergy.com email: OCD Only Received by: Dylan Rose-Coss Date: 07/05/2019

Location:	Mis Amigos Battery (Fire) (30	0-025-40590)	
Spill Date:	6/18/2019		
Approximate Ar	ea=	900	lft ²

Approximate Oil %	100
Average Porosity Factor=	0.03

VOLUME OF I	LEAK
Total Oil=	0.05 barre
Total Produced Water=	0.00 barre