

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**State of New Mexico**  
**Energy Minerals and Natural**  
**Resources Department**  
**Oil Conservation Division**  
**1220 South St. Francis Dr.**  
**Santa Fe, NM 87505**

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NRM1932238401
District RP	2RP-5699
Facility ID	
Application ID	pRM1932239200

## Release Notification

# ID3TN-191014-C-1410

### Responsible Party

Responsible Party	XTO Energy	OGRID	5380
Contact Name	Kyle Littrell	Contact Telephone	432-221-7331
Contact email	Kyle_Littrell@xtoenergy.com	Incident #	(assigned by OCD)
Contact mailing address	522 W. Mermod, Carlsbad, NM 88220		

### Location of Release Source

Latitude 32.096429 Longitude -103.864004  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	PLU 421	Site Type	Well Site
Date Release Discovered	10/04/2019	API# (if applicable)	30-015-41033 (Poker Lake Unit 421 H)

Unit Letter	Section	Township	Range	County
P	27	25S	30E	EDDY

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls)	0.01	Volume Recovered (bbls)	0.0
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls)	6.02	Volume Recovered (bbls)	0.0
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		<input type="checkbox"/> Yes <input type="checkbox"/> No	
<input type="checkbox"/> Condensate	Volume Released (bbls)		Volume Recovered (bbls)	
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)		Volume Recovered (Mcf)	
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)		Volume/Weight Recovered (provide units)	

Cause of Release: Lease Operator found a release at the compressor suction line. A weld failed on the 4" poly line. Release impacted pad surface soil with nothing recovered. Additional third party resources have been retained to assist in the remediation.


State of New Mexico  
Oil Conservation Division

Incident ID	NRM1932238401
District RP	2RP-5699
Facility ID	
Application ID	pRM1932239200

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  N/A
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?  N/A	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:  There were no free fluids contained via the use of berms or dikes, absorbent pads, or other containment devices. No fluid remained to be removed.	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kyle Littrell</u>	Title: <u>SH&amp;E Supervisor</u>
Signature: 	Date: <u>10/14/2019</u>
email: <u>Kyle_Littrell@xtoenergy.com</u>	Telephone: _____
<b><u>OCD Only</u></b>	
Received by: <u>Ramona Marcus</u> Date: <u>11/18/2019</u>	