Boring or excavation logs

☐ Topographic/Aerial maps

Photographs including date and GIS information

Laboratory data including chain of custody

Form C-141 Page 3

State of New Mexico Oil Conservation Division

Incident ID	NAB1915028224
District RP	1RP-5511
Facility ID	
Application ID	pAB1915027889

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	129 (ft bgs)		
Did this release impact groundwater or surface water?	☐ Yes ⊠ No		
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ⊠ No		
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ⊠ No		
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ⊠ No		
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ⊠ No		
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ⊠ No		
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ⊠ No		
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ⊠ No		
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ⊠ No		
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ⊠ No		
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ⊠ No		
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ⊠ No		
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.			
Characterization Report Checklist: Each of the following items must be included in the report.			
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.			
Field data Data table of soil contaminant concentration data			
Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release			
—			

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Form C-141 Page 4

State of New Mexico Oil Conservation Division

Incident ID	NAB1915028224
District RP	1RP-5511
Facility ID	
Application ID	pAB1915027889

public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a factor of the contamination of	the best of my knowledge and understand that pursuant to OCD rules and notifications and perform corrective actions for releases which may endanger the OCD does not relieve the operator of liability should their operations have threat to groundwater, surface water, human health or the environment. In of responsibility for compliance with any other federal, state, or local laws
Printed Name: <u>Isaac Castro</u> T	Citle: Environmental Professional
Signature: Asaac Castro	Date:
email: <u>icastro@marathonoil.com</u>	Telephone: <u>575-988-0561</u>
OCD Only	
Received by: Cristina Eads	

Form C-141 Page 6

State of New Mexico Oil Conservation Division

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

Incident ID	NAB1915028224
District RP	1RP-5511
Facility ID	
Application ID	pAB1915027889

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
 ☑ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection) ☑ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling) 		
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of a should their operations have failed to adequately investigate and reme human health or the environment. In addition, OCD acceptance of a compliance with any other federal, state, or local laws and/or regulative restore, reclaim, and re-vegetate the impacted surface area to the concaccordance with 19.15.29.13 NMAC including notification to the OC	ediate contamination that pose a threat to groundwater, surface water, C-141 report does not relieve the operator of responsibility for ons. The responsible party acknowledges they must substantially ditions that existed prior to the release or their final land use in D when reclamation and re-vegetation are complete.	
Printed Name: <u>Isaac Castro</u> Title Signature: <u>Asaac Castro</u>	Environmental Professional	
Signature: Vsaac Castro	Date:7-16-19	
email: <u>icastro@marathonoil.com</u>	Telephone: <u>575-988-0561</u>	
OCD Only		
Received by: Cristina Eads	Date: 01/14/2020	
	f liability should their operations have failed to adequately investigate and ater, human health, or the environment nor does not relieve the responsible regulations.	
Closure Approved by: Orthol	Date:	
Printed Name: Cristina Eads	Title: 01/14/2020	
<u> </u>		