

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Plains Pipeline, LP	Contact	Camille Bryant
Address	1911 Connie Road	Telephone No.	575-441-1099
Facility Name	Mewbourne Mad Dog 26 MP State Com #001H	Facility Type	Lact Unit
Surface Owner	NMSLO	Mineral Owner	NMSLO
		API No.	

### LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	23S	34E					

Latitude 32.2687600 Longitude -103.4482740 NAD83

### NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	9 bbls	Volume Recovered	6 bbls
Source of Release	Triplex Pump	Date and Hour of Occurrence	8/19/2018 @ 2:45 PM	Date and Hour of Discovery	8/19/2018 @ 2:45 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Olivia Yu		
By Whom?	Camille Bryant	Date and Hour	8/20/2018 @ 12:40 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Mechanical failure on the Triplex pump that resulted in a sheared bolt.					
Describe Area Affected and Cleanup Action Taken.* Impacted area includes bermed lact unit and adjacent production pad. Release area was remediated per current NMOCD guidelines.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Amber Groves	Approved by Environmental Specialist: <i>Bradford Billings</i>		
Title: Remediation Coordinator	Approval Date: 01/13/2020	Expiration Date:	
E-mail Address: algroves@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 1/22/2019 Phone: (575)200-5517	NA		

\* Attach Additional Sheets If Necessary