

KIL-TEX OILFIELD SERVICES LLC

U.S. DOT#: 1954711

Address: 524 GLADEWATER STREET

KILGORE, TX 75662 Number of Vehicles: 10 Number of Drivers: 4 Number of Inspections: 7

Safety Rating & OOS Rates

(As of 03/22/2020 updated daily from SAFER)

SATISFACTORY

(Rating Date: 05/16/2014)

Out of Service Rates

Туре	00S %	National Avg %
Vehicle	42.9	20.7
Driver	14.3	5.5
Hazmat		4.5

Licensing and Insurance

(As of 03/22/2020 updated hourly from L&I)

Active For-Hire Authority

Туре	Yes/No MC#/MX#								
Property	Yes	MC- 859500							
Passenger	No								
Household Goods	No								
Broker	No								

BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICs)













Based on a 24-month record ending February 28, 2020



Not Public

Unsafe Driving

Crash Indicator

Hours-of-Service Compliance

Vehicle Maintenance

Controlled Substances and Alcohol

Not Public Hazardous Materials Compliance

Driver Fitness

On-Road Performance

1.03 Measure	NOT	1.40 Measure	6.20 Measure	0 Measure	NOT	0 Measure
	PUBLIC				PUBLIC	

On-Road Performance Detail

Driver Inspections with **Unsafe Driving** Violations: 1

Safety Event **Group:** No Safety **Event Grouping**

Avg. PU × UF: 9.7

Segment: Combination Carrier

Driver with HOS Compliance Violations: 1 Safety Event

Inspections: 7 **Group:** 3-10 relevant driver inspections

Vehicle Inspections: 7 with Vehicle Maint. Violations: 4 **Safety Event Group:** 5-10 relevant vehicle inspections

Driver Inspections: 7 with Drugs/Alcohol Violations: 0 Safety Event **Group:** No Safety **Event Grouping**

NOT **PUBLIC**

Driver Inspections: 7 with Driver **Fitness** Violations: 0 **Safety Event Group:** 5-10 relevant driver inspections

NOT

PUBLIC

Investigation Results

No Acute/Critical Violations Discovered

N/A

No Acute/Critical Violations Discovered No Acute/Critical Violations Discovered No Acute/Critical Violations Discovered

NOT PUBLIC No Acute/Critical Violations Discovered

Select a BASIC icon above to get details, or view your **Complete SMS Profile**.

Summary of Activities

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation: 5/15/2014 (Compliance Review)

Total Inspections: 7

Total Inspections without Violations used in SMS: 2 Total Inspections with Violations used in SMS: 5

Total Crashes*:1

*Crashes listed represent a motor carrier's involvement in reportable crashes, regardless of the carrier's or driver's role in the crash. Continue for details.

Carrier Registration

Subject to General Threshold

Enforcement Cases

(Six years as of 03/22/2020 updated monthly from <u>FMCSA</u>)

No penalties found

USE OF SMS DATA/INFORMATION

FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at http://safer.fmcsa.dot.gov and motor carrier licensing and insurance status are available at http://li-public.fmcsa.dot.gov/.