

NM1-62

**Permit
Application**

**Volume 4
Part 4 of 11**

**COMPLETION REPORT
SUPPLEMENTAL DRILLING AND SAMPLING**

**SUNDANCE SERVICES, INC.
LEA COUNTY, NEW MEXICO**

**ATTACHMENT A
PROJECT PHOTOGRAPHS**



Photograph 1. Rodgers set up on CH-1 with CME-75 HSA and related equipment.



Photograph 2. HSA drilling and continuous core sampling CH-1. Driller and helper each holding 5-foot long sampler.



Photograph 3. Core sample of CH-1 at the base of the OAG and top of Chinle.



Photograph 4. Core sample of CH-1 at top of Chinle.

PROJECT PHOTOGRAPHS

SUNDANCE WEST
SUNDANCE SERVICES INC
LEA COUNTY, NEW MEXICO



Gordon Environmental, Inc.
Consulting Engineers

213 S. Camino del Pueblo
Bernalillo, New Mexico, USA
Phone: 505-867-6990
Fax: 505-867-6991

DATE: 12/08/09	CAD: SSI-PROJECT PICS.doc	PROJECT #: 235.01.02
DRAWN BY: PG	REVIEWED BY: AY	ATTACHMENT A
APPROVED BY: IKG	gei@gordonenvironmental.com	(SHEET 1 OF 9)