

NM1-62

**Permit
Application**

**Volume 4
Part 6 of 11**



Photograph 13. Core sample of claystone (Chinle) in CH-2.



Photograph 14. Core sample of claystone with grey clay inclusions (Chinle) in CH-2.



Photograph 15. Rodgers set up to drill CH-3.



Photograph 16. Core sample of surface sand in CH-3.

PROJECT PHOTOGRAPHS

SUNDANCE WEST
SUNDANCE SERVICES INC
LEA COUNTY, NEW MEXICO



Gordon Environmental, Inc.

Consulting Engineers

213 S. Camino del Pueblo
Bernalillo, New Mexico, USA
Phone: 505-867-6990
Fax: 505-867-6991

DATE: 12/08/09	CAD: SSI-PROJECT FIGS.doc	PROJECT #: 235.01.02
DRAWN BY: PG	REVIEWED BY: AY	ATTACHMENT A (SHEET 4 OF 9)
APPROVED BY: IKG	gei@gordonenvironmental.com	