


NM1-62

**Permit
Application**

**Volume 4
Part 7 of 11**



Photograph 17. Core sample of caliche in CH-3.



Photograph 18. Core sample of root fibers in caliche in CH-3.



Photograph 19. Core sample of base of OAG and top of Chinle in CH-3.



Photograph 20. Core sample claystone (Chinle) in CH-3.

PROJECT PHOTOGRAPHS

SUNDANCE WEST
SUNDANCE SERVICES INC.
LEA COUNTY, NEW MEXICO



Gordon Environmental, Inc.
Consulting Engineers

213 S. Camino del Pueblo
Bernalillo, New Mexico, USA
Phone: 505-867-6990
Fax: 505-867-6991

DATE: 12/08/09	CAD: SSI-PROJECT PICS.doc	PROJECT #: 235.01.02
DRAWN BY: PG	REVIEWED BY: AY	ATTACHMENT A
APPROVED BY: JKG	gei@gordonenvironmental.com	(SHEET 5 OF 9)