NM - ZZ

INSPECTIONS & DATA

Stake BF Dispose Pi Unit of Section 16 - Location Goodwill Februsia The 20s, RSSE Leccounty Repair Medis Permil #18594 Repair Medis Permil	Rube # 23- Photo # 23- Photo # 23- Photo # 23- Tank Both Tank Both Find to
---	--






PHOTO NO. 1 DATE: 04/1/97



PHOTO NO. 2 DATE: 04/1/97



PHOTO NO. 3 DATE: 04/1/97




PHOTO NO. 4 DATE: 04/1/97



PHOTO NO. 5 DATE: 04/1/97



PHOTO NO. 6 DATE: 04/1/97



PHOTO NO. 7 DATE: 04/1/97



PHOTO NO. 8 DATE: 04/1/97



PHOTO NO. 9 DATE: 04/1/97



PHOTO NO. 10 DATE: 04/1/97






PHOTO NO. 11 DATE: 04/1/97

PHOTO NO. 12 DATE: 04/1/97



PHOTO NO. 13 DATE: 04/1/97




PHOTO NO. 14 DATE: 04/1/97




PHOTO NO. 15

DATE: 04/1/97









Injection Well

oso fallada bilans e.

16/95-



Petrothermo tanks 3/16/95



Petrothermo tanki 3/16/95



Petrothormo tank leaks 3/16/95

AL DESERT BARRES



Petrothermo tanks 3/16/95

0.040



Petrothermo tanks & old SE pit 3/16/95

(). ())



Petrothermo tanks 3/16/95

ii S S



TO STREET SET SEC

Reta thorms
3/16/95



PetroHermo Tanks 3/16/95

Towns of the state of the state







Petrothermo west tank



Petro thermo Tanks 3/16/95



Petrothormo Tanks 3/16/95



Petro thermo Looking East 3/16/95



Petrothermal Inc Treating Plant Agua Inc SWO





3





Petrothorms injection pump 3/16/95





4-1-97







Petrothermal Treating Plant







4-1-97

1.1





