

HBP - 9

MONITORING REPORTS

YEAR(S):

1999 - 1993

SID RICHARDSON GASOLINE CO.

201 MAIN STREET, SUITE 3000
FORT WORTH, TEXAS 76102


ROBERT L. GAWLIK
ENVIRONMENTAL HEALTH
& SAFETY ASSOCIATE

817/390-8600

March 16, 1999
RLG-10-99

CERTIFIED MAIL – RETURN RECEIPT
Z 218 890 258

Mr. Roger Anderson
New Mexico Energy, Minerals and
Natural Resources Department
Oil Conservation Division
2040 S. Pacheco
Santa Fe, New Mexico 87505



**Re: Hydrostatic Test Water Discharge Annual Report
Permit (HBP-NM-009)**

Dear Mr. Anderson:

Sid Richardson Gasoline Co. is submitting this annual report pursuant to Section 1-201 of the New Mexico Water Quality Control Commission and the conditions set in our hydrostatic test water discharge permit (HBP-NM-009) (January 22, 1998).

In 1998, there were two (2) pipeline projects requiring hydrostatic testing. The information on these two lines is as follows:

Date of Test: **05-13-98** Hydro Test Conducted By: **Flint Engineering**
Location of Test: **Section 12** **Township 26** **Range 30**
Volume of Potable Water: **98,070 gal.** Source of Water: **Lindsey Water Station**
Water Analysis Conducted By: **Martin Water Labs** Pipe Used: **New**

Date of Test: **11-20-98** Hydro Test Conducted By: **Floyd Sims Construction**
Location of Test: **Section 6** **Township 23** **Range 31**
Volume of Potable Water: **73,000 gal.** Source of Water: **Mills Water Station**
Water Analysis Conducted By: **Martin Water Labs** Pipe Used: **New**

Attached are copies of the water analysis conducted by Martin Water Labs as requested.

If there are any questions concerning this report, please do not hesitate to call me at 817-390-8685.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert L. Gawlik", is written over a horizontal line.

Robert L. Gawlik
Environmental Health & Safety Associate

RLG:kmb
c: CPO/HH/MRR/WJF w/o attachments
R. Dunn – Lea County Gathering w/attachments
Wayne Price – OCD Hobbs Office w/attachments

P. O. BOX 1466
MONAHANS, TEXAS 79756
PH. 943-3234 OR 563-1040

Martin Water Laboratories, Inc.

709 W. INDIANA
MIDLAND, TEXAS 79701
PHONE 683-4621

RESULT OF WATER ANALYSES

TO: Mr. Gary Hobson LABORATORY NO. 598105
P.O. Box 1226, Jal. NM 88252 SAMPLE RECEIVED 5-13-98
RESULTS REPORTED 5-14-98

COMPANY Sid Richardson Gasoline Company LEASE Burlington El Paso #2

FIELD OR POOL _____

SECTION _____ BLOCK _____ SURVEY _____ COUNTY Lea STATE NM

SOURCE OF SAMPLE AND DATE TAKEN:

NO. 1 Hydrotest water - taken @ Lindsey Water Station. 5-13-98

NO. 2 _____

NO. 3 _____

NO. 4 _____

REMARKS:

CHEMICAL AND PHYSICAL PROPERTIES

	NO. 1	NO. 2	NO. 3	NO. 4
Specific Gravity at 60° F.	1.0030			
pH When Sampled				
pH When Received	7.98			
Bicarbonate as HCO ₃	132			
Supersaturation as CaCO ₃				
Undersaturation as CaCO ₃				
Total Hardness as CaCO ₃	850			
Calcium as Ca	252			
Magnesium as Mg	53			
Sodium and/or Potassium	164			
Sulfate as SO ₄	306			
Chloride as Cl	334			
Iron as Fe	0.04			
Barium as Ba				
Turbidity, Electric				
Color as Pt				
Total Solids, Calculated	1.462			
Temperature °F.				
Carbon Dioxide, Calculated				
Dissolved Oxygen				
Hydrogen Sulfide	0.0			
Resistivity, ohm-cm at 77° F.	4.19			
Suspended Oil				
Filtrable Solids as mg/l				
Volume Filtered, ml				
Nitrate, as N	3.6			

Results Reported As Milligrams Per Liter

Additional Determinations And Remarks The undersigned certifies the above to be true and correct to the best of his knowledge and belief.

SID RICHARDSON GASOLINE CO.
201 MAIN STREET, SUITE 3000
FORT WORTH, TEXAS 76102


ROBERT L. GAWLIK
ENVIRONMENTAL HEALTH
& SAFETY ASSOCIATE

817/390-8600

January 30, 1998
RLG-20-98

CERTIFIED MAIL - RETURN RECEIPT
P 115 630 447

Martyne Kieling
New Mexico Energy, Minerals and
Natural Resources Department
Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87504-2088



Dear Martyne:

On January 2, 1998, SRGCo. submitted to the OCD a request for the renewal of our current five-year authorization for the discharge of hydrostatic test waters in Lea County, New Mexico. As per our telephone conversation on January 26, 1998, you requested that an annual statement be sent to you for all new pipe that was hydrostatic tested for the years 1995, 1996 and 1997. The following is furnished for your records:

1995 - No new pipe was hydrostatic tested in 1995.

1996 - Two (2) tests were conducted in February 1996, and a total of 107,900 gallons of fresh water were discharged onto the ground.

Test 1 - Section 24, TS 25S, Range 33E. Discharged 37,900 gallons of fresh water.

Test 2 - Section 25, TS 25S, Range 33E. Discharged 70,000 gallons of fresh water.

1997 - One (1) test was conducted in October 1997, and a total of 30,027 gallons of fresh water discharged onto the ground.

Test 1 - Section 2, TS 25 S, Range 31E. Discharged 30,027 gallons of fresh water.

W/K
2/1/98

Martyne Kieling
RLG-20-98; 01/30/98
Page Two

We apologize for any inconvenience this lack of information may have caused. If other information is required or if there are any questions that you may have, please do not hesitate to call me.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert L. Gawlik", with a stylized flourish at the end.

Robert L. Gawlik
Environmental, Health & Safety Associate

RLG:gdw

c: C. P. O'Farrell/H. Harless
W. J. Farley
K. C. Clark
H. E. Hicks

OIL CONSERVATION DIVISION
RECEIVED SID RICHARDSON GASOLINE CO.
201 MAIN STREET, SUITE 3000
FORT WORTH, TEXAS 76102
1994 MAY 11 AM 8 50

MICHAEL J. MCCONNELL
COMPLIANCE COORDINATOR
ENVIRONMENTAL HEALTH & SAFETY

817/390-8600

May 6, 1994
MJM-32-94
File: NM-9

CERTIFIED MAIL - RETURN RECEIPT
P 378 679 211

Mr. Roger Anderson
New Mexico Energy, Minerals &
Natural Resources Department
Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87504

Re: New Pipeline Hydrostatic Test Discharge Report

Dear Mr. Anderson:

In accordance with reporting requirements established under OCD testwater discharge guidelines, the following summarizes new pipeline hydrostatic test activities conducted by Sid Richardson Gasoline Co. over the past six months since November 8, 1993.

- 1) **Date of Test:** January 25, 1994
Test Location: Section 13, Township 25S, Range 30E, Eddy County, New Mexico
Discharge Volume: 100,000 gallons

Test Water Source & Quality: Fresh water drawn from the Diamond and A-Half Ranch water supply. Mr. Carl Johnson, owner.
P. O. Box 1299
Jal, New Mexico 88252

- 2) **Date of Test:** February 3, 1994
Test Location: Section 1, Township 25S, Range 30E, Eddy County, New Mexico
Discharge Volume: 9,150 gallons

Test Water Source & Quality: Fresh water drawn from the Diamond and A-Half Ranch water supply. Mr. Carl Johnson, owner.
P. O. Box 1299
Jal, New Mexico 88252

Mr. Roger Anderson
New Pipeline Hydrostatic Test Discharge Report
MJM-32-94; 05/06/94
PAGE TWO

If you have any questions regarding this report, don't hesitate to call me.

Sincerely,

A handwritten signature in black ink that reads "Michael J. McConnell". The signature is written in a cursive style with a large, stylized "M" and "C".

Michael J. McConnell
Compliance Coordinator
Environmental Health & Safety
(817) 338-8386

MJM:gad

OIL CONSERVATION DIVISION
RECEIVED

'93 NOV 12 AM 9 23

SID RICHARDSON CARBON & GASOLINE CO.
FIRST CITY BANK TOWER
201 MAIN STREET
FORT WORTH, TEXAS 76102

MICHAEL J. McCONNELL
COMPLIANCE COORDINATOR
ENVIRONMENTAL HEALTH & SAFETY

817/390-8600

November 8, 1993
MJM-118-93
File: NM-9

CERTIFIED MAIL - RETURN RECEIPT

P 452 757 041

Mr. Roger Anderson
New Mexico Energy, Minerals &
Natural Resources Department
Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87504

Subject: New Pipeline Hydrostatic Test Discharge Report

Dear Mr. Anderson:

In accordance with reporting requirements established under OCD testwater discharge guidelines, the following summarizes new pipeline hydrostatic test activities conducted by Sid Richardson Gasoline Co. over the past six months.

- 1) **Date of Test:** April 7, 1993
Test Location: Sid Richardson Jal 3 plant, NW/4 SW/4, Section 33, Township 24S, Range 37E, Lea County, New Mexico
Discharge Volume: 27,000 gallons

Test Water Source & Quality: Fresh water drawn from Sid Richardson's Jal 3 water well system.
- 2) **Date of Test:** October 29, 1993
Test Location: Section 34, Township 26S, Range 29E, Eddy County, New Mexico
Discharge Volume: 84,000 gallons

Test Water Source & Quality: Well water drawn from the CRW-SWD Inc. fresh water station located in Section 26, Township 26S, Range 29E, Eddy County, New Mexico

Mr. Roger Anderson
New Pipeline Hydrostatic Test Discharge Report
MJM-118-93; 11/08/93
PAGE TWO

Should you have any questions regarding this report, don't hesitate to call.

Sincerely,

A handwritten signature in black ink that reads "Michael J. McConnell". The signature is fluid and cursive, with the first name "Michael" and last name "McConnell" clearly legible.

Michael J. McConnell
Compliance Coordinator
Environmental Health & Safety
(817) 338-8386

MJM:gad

cc: C. P. O'Farrell/E. F. Gunn
W. J. Farley
T. E. McElyea/C. E. Adcock/M. A. Lopez/C. M. Davenport
K. C. Clark
G. W. Washburn