# HIP - 81

# GENERAL CORRESPONDENCE

YEAR(S): 2002

Offic Rece	cial Receipt eived from: <u>R</u>	Construction of the second second		Date: <u>//-/4</u> Dollar Amount _ 📿	-19 <u>2002</u> 50.00
DR CR.	AMOUNT NUMBER	CENTER NUMBER	CREDIT AMOUNT	DEPOSIT NUMBER	WORK ORDER NO.
60	4290				
60	4291				
60	3450				
60	3451	and the second			
60	3410				
60	4210				
60	4240				
60					
60					
60	r				
60					
		TOTAL	250.00		

# ACKNOWLEDGEMENT OF RECEIPT OF CHECX/CASH

٠.

I hereby acknowledge receipt	of check No. 106547 dated 11-4-02
	in the amount of $$2.50$ .00
from PNM Electric & Gas So	
for Hydrostatic test HI-	
Submitted by: PNM	Date:
Submitted to ASD by: Martyne	KiclingData:
Received in ASD by:	Data:
Filing Feet New Fac	ility Renewal
	Tempomoy Permit HI-081 \$150
Organization Code <u>521.07</u>	Applicable FY 2003
To be deposited in the Water ( Full Payment or An	Quality Management Fund.
	101AL \$250.00
606 106547 <b>PNIN</b>	ULTICOLORED BACKGROUND ON WHITE PAPER
Electric and Gas Services	CHECK NO DATE AMOUNT
General Fund Account	106547 110402 \$******250.00
WATER QUALITY MANAGEMENT FUND PAY C/O OIL CONSEVATION DIVISION TO THE 1220 NORTH ST. FRANCIS DRIVE ORDER SANTA FE, NM 87505 OF	Authorized Signature

#106547# #092904774# 4800364#

1.6.1

#### NEW MEXICO ENVIRONMENT DEPARTMENT REVENUE TRANSMITTAL FORM

	ENUE INA		DFA ORG	ACCT	ED ORG	ED ACCT	AMOUNT	
Description	FUND	CES	Ond					
1 CY Reimbursement Project Tax	064	01						
5 Gross Receipt Tax	064	01	-	2329	900000	2329134		
THE THE THE THE	092	13	1300	1696	900000	4169134		
3 Air Quality Litle V 4 PRP Prepayments	248	14	1400	9696	900000	4969014		
	248	14	1400	9696	900000	4989015		
	248	14	1400	9696	900000	4969248		;
7 Hazardous Waste Permits	339	27	2700	1696	900000	4169027		
8 Hazardous Waste Annual Generator Fees	339	27	2700	1696	800000	4169339	\$ 2 - 00	1
the second secon	341	29		2329	900000	2379029	\$250.00	1(
	341	29	2900	1696	900000	4169029		<u><u></u><u></u></u>
	631	31	2500	1596	900000	4169031		12
	851	33		2919	000000	2919033		12
	652	34		2349	900000	2349001		*14
*14 Xerox Copies	652	34		2349	900000	2349002		15
15 Ground Water Penalties	652	34		2349	800000	2439003		16
16 Witness Fees	652	34		2349	900000	2349004		17
17 Air Quality Penalties	652	34		2349	900000	2349005		18
18 OSHA Penalties	652	34		2349	900000	2349005		19
19 Prior Year Reimbursement	652	34		2349	900000	2349009		20
20 Surface Water Quality Certification	852	34		2349	900000	2349012		21
21 Jury Duty	652	34		2349	900000	2349014		22
22 CY Reimbursements ( I.e. telephone)	783	24	2500	9690	900000	4969201		•23
*23 UST Owner's List		24 24	2500	9696	800000	4969202		-24
*24 Hazardous Waste Notifiara List	783	24 24	2500	9696	000000	4989203		*25
*25 UST Maps	783		2500	9696	900000	4989205		*2ô
*26 UST Owner's Update	783	24	2500	2696	900000	4969207		-28
*28 Hazardous Waste Regulations	783	24	2500	9696	900000	4909208		*29
29 Radiologic Tech. Regulations	783	24	2500 2500	9696	900000	4869211		*30
*30 Superfund CERLIS List	783	24		9696	900000	4969213		31
31 Solid Waste Permit Fees	783	24	2500	9696 9696	900000	4959214		32
32 Smoking School	783	24	2500		900000	4969222		*33
*33 SWQB - NPS Publications	783	24	2500	9696	900000	4969228		*34
*34 Radiation Licensing Regulation	783	24	2500	9696		4969301		*35
35 Sale of Equipment	783	24	2500	9596	900000	4969302		*38
36 Sale of Automobile	783	24	2500	9696	000000			+137
*37 Lust Recoveries	783	24	2500	9698	000000	4969614		**38
*38 Lust Repayments	783	24	2500	9696	900000	4969815		39
39 Surface Water Publication	783	24	2500	9696	900000	4969801		39 40
40 Exxon Reese Drive Ruidoso - CAF	783	24	2500	9695	900000	4969242	- <u></u>	
41 Emerg. Hazardous Waste Penalties NOV	957	32	9600	1898	900000	4164032		41
42 Radiologic Tech. Certification	987	05	0500	1898	900000	4169005		42
44 Ust Permit Fees	988	20	3100	1696	900000	4169020	······	44
45 UST Tank Installers Fees	989	20	3100	1696	800000	4169021		45
	991	26	2600	1696	900000	4169026		46
						والمتحادث والمتحر وسيادي وسير		43
48 Food Permit Fees 43 Chher		20					2.57).00	

Gross Receipt Tax Required

- Site Name & Project Code Required

TOTAL 250.

Contact Person: Rocer C. Anderson	Phone:	476-3490 Date:	11-14-02
Received in ASD BV	Date:		ST # :


AND REAL MARKED AND AND AND AND ADDRESS OF A REAL AND A

FSB025 Revised 07/07/00

M C DO

1. 6. 11 1

Q F 4 7 1



### TRANSMITTAL COVER SHEET

OIL CONSERVATION DIVISION 1220 S. ST. FRANCIS DRIVE SANTA FE, NM 87505 (505) 476-3440 (505)476-3462 (Fax)

PLEASE DEL	LIVER THIS FAX:	
TO:	Robin Delapp	505-241-2376 Fax
FROM:	Martyre Kicling	
DATE:	11-14-02	
PAGES:	1053	
SUBJECT:	Hydrotest	
······································	· · · · · · · · · · · · · · · · · · ·	

IF YOU HAVE TROUBLE RECEIVING THIS FAX, PLEASE CALL THE OFFICE NUMBER ABOVE.

The large stand with a stand of the stand stand of the stand stan



RECEIVED

NUA 0 8 5005

Environmental Bureau Oil Conservation Division



A personal commitment to New Mexico

3617 11

PNM Alvarado Square Albuquerque, NM 87158-2104 Fax 505 241-2376 www.pnm.com

CERTIFIED MAIL No. 7099 3220 0005 5958 4408 RETURN RECEIPT REQUESTED

November 5, 2002

Martyne Kieling State of New Mexico Oil Conservation Division 1220 South St. Francis Drive Santa Fe, NM 87505

RE: PNM Alamogordo Natural Gas Mainline Notice of Intent to Hydrostatically Test and Discharge

Dear Ms. Kieling:

Public Service Company of New Mexico (PNM) intends to hydrostatically test 7.25 miles of existing 6-inch natural gas pipeline from PNM's Chaparral Compressor Station (T26S, R5E, Section 33) to Block Valve Setting 1 (T25S, R5E, Section 27) in Dona Ana County, New Mexico (see attached map). The project area is located approximately 26 miles southeast of Las Cruces, New Mexico. This line was recently repaired and must be tested prior to being placed back into service.

The test is scheduled for November 2002 pending approval from your office and selection of a contractor. The proposed test will consist of hydrostatic testing approximately 38,280 feet of 6-inch steel natural gas pipeline and will include a) water injection to be preceded by a pig to eliminate air pockets, b) replacement of any sections that are damaged due to line rupture, c) hydrostatic re-testing of each section after completion of each repair resulting from a line rupture, and d) post-test pigging after initial dewatering.

Approximately 57,450 gallons (1.5008 gallons/lineal feet x 7.25 miles x 5,280 feet/mile) of water from a potable water source will be used in the test. The test water will be discharged from the pipeline at a point to be determined. Any fluids or solids will be collected and tested prior to disposal in accordance with 40 CFR 261 for metals, volatiles, and semi-volatiles. The used test water will be trucked to and disposed of at an approved and permitted surface waste management facility to be determined. PNM will obtain an OCD C-138 form from the disposal facility since the waste stream is non-exempt.

According to State Engineer well records, the recorded depth to water along the length of pipeline to be tested ranges from an average of 326 to 410 feet.

Enclosed is a check for \$250.00 (\$100 for the filing fee and \$150 for temporary permission). Thank you in advance for your assistance and quick issuance of this permit. If there is anything we can do to expedite the process we will do so. Please call me at (505) 241-2016 if you have any questions.

THE FACTOR HA


Sincerely,

ben K. De Lapp

Robin DeLapp Senior Environmental Scientist

Attachment: Location map

Cc: Regina Bacaoan, PNM Southern Engineering ESD/DCC



PNM Alvarado Square Albuquerque, NM 87158-2104 Fax 505 241-2376 www.pnm.com

#### CERTIFIED MAIL No. 7099 3220 0005 5958 4583 RETURN RECEIPT REQUESTED

November 5, 2002

Mike Stubblefield Oil Conservation Division District 2, Artesia 1301 W. Grand Avenue Artesia, NM 88210

RE: PNM Alamogordo Natural Gas Mainline Release Notification

Dear Mr. Stubblefield:

Public Service Company of New Mexico (PNM) is hereby filing two copies of a completed Division Form C-141 (Release Notification and Corrective Action) to make written notice of a natural gas release from a pipeline rupture. PNM gave verbal notice to Martyne Kieling of the OCD, Santa Fe Office on September 30, 2002. The release of natural gas occurred when PNM's 6-inch Alamogordo Natural Gas Pipeline ruptured. The rupture occurred in T25S, R5E, Section 34 approximately 26 miles southeast of Las Cruces, Dona Ana County, New Mexico.

Please call me at (505) 241-2016 if you have any questions.

Sincerely,

Zobri K. Detapp

Robin K. DeLapp Senior Environmental Scientist

Attachment: C-141 Form

Cc: Martyne Kieling, OCD Santa Fe. Regina Bacaoan, PNM Southern Engineering ESD/DCC



A personal commitment to New Mexico





• • • • <del>و</del>	<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	State of New Mexico Energy Minerals and Natural Resources Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505	Form C-141 Revised March 17, 1999 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
•	F	Release Notification and Corrective Action	
		OPERATOR	Initial Report X Final Repo

	UPERATOR	Initial Report	X Final Report
Name of Company PNM	Contact Wil Nez		
Address 414 Silver SW Albuquerque, NM 87102	Telephone No, 505/241-4873		
Facility Name Alamogordo Mainline	Facility Type Natural Gas Pipe	line	
Surface Owner N/A	Mineral Owner N/A	Lease No. N/A	

LOCATION OF RELEASE								
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N/A	34	255	5E	N/A	N/A	N/A	N/A	Dona Ana County

NATURE	OF RELEASE						
Type of Release Pipeline Rupture	Volume of Release Volume Recovered 0						
Source of Release PNM pipeline	Date and Hour of Occurrence 9/22/02 1:30 a.m. Date and Hour of Discovery 9/23/02 8:50 a.m.						
Was Immediate Notice Given?	If YES, To Whom?						
By Whom?	Date and Hour						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*							
N/A							
Describe Cause of Problem and Remedial Action Taken.*							
No liquids or fluids were observed or came in contact with the surrounding soil so no remedial action was taken or is planned.							
Describe Area Affected and Cleanup Action Taken.*							
N/A							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.							
Signature: Sem Revela	OIL CONSERVATION DIVISION						
Printed Name: LATTY Riverdan	Approved by District Supervisor:						

Approval Date:


Expiration Date:

Attached

	Date:	11/1/02	Phone: 505/443-6417	Conditions of Approval:
*	Attach Add	ditional Sheets If Nec	essary	

Operations Supervisor

Title:



Alamogordo Mainline

# Kieling, Martyne

From:Kieling, MartyneSent:Monday, September 30, 2002 3:28 PMTo:Stubblefield, Mike

Subject: FW: Alamogordo Mainline

Mike,

FYI.

I had a phone call today from Robin DeLapp with PNM. They had a Gas line Rupture last week. There was not explosion and no fire it was in a remote area I was told. Robin also mentioned that it blew a 8 foot trench 40 feet long. Robin just sent me the legal and I have not looked at a map as of yet. PNM will be running a hydrostatic test once the repairs are made. They will be sending me the information in order to acquire a Permit to discharge the water. The 6" pipe line was put into service in 1954 and their engineers are expecting that it may rupture during the test. Robin Had some questions regarding spill reporting in case this happens.

See you tomorrow. Martyne

-----Original Message-----From: Kieling, Martyne Sent: Monday, September 30, 2002 3:20 PM To: 'DeLapp, Robin' Subject: RE: Alamogordo Mainline

Robin,

Thank you for the Location. And you understood my message correctly. I will look for your permit application and process in a timely manner.

Martyne.

-----Original Message----- **From:** DeLapp, Robin [mailto:RDELAPP@pnm.com] **Sent:** Monday, September 30, 2002 3:18 PM **To:** 'mkieling@state.nm.us' **Subject:** Alamogordo Mainline

#### Martene,

The area of the Alamogordo Mainline that we were discussing earlier is approximately 26 miles southeast of Las Cruces. The 8-mile segment that may be tested (that length may change) includes (from north to south): T26S, R5E, Sections 33, 28, 21, 16, 9, and 4 and T25S, R5E, Sections 27, 33, 34.

It is my understanding from your phone message that if a rupture occurs during the hydrostatic tests that we must 1) complete Form C-141 (Release Notification and Corrective Action Form) and 2) notify the closest local field office, that would Artesia. Thanks again for your help.

Robin DeLapp Public Service Company of New Mexico Alvarado Square, Mail Stop 2104 Albuquerque, New Mexico 87158

phone: (505) 241-2016/ fax: (505) 241-2376 • cell: (505) 362-0730/ email: rdelapp@pnm.com

