1R - 155

GENERAL CORRESPONDENCE

YEAR(S):

1995-1992

#11. ##MSERLATION DIVISION RELE ションD

195 JA4 7:3 117 8 52

ENRON OPERATIONS CORP.

P. O. Box 1188 Houston, Texas 77251-1188 (713) 853-6161

53-6161

VIA CERTIFIED MAIL: P 362 442 889

January 10, 1995

¥ .. 🕯

Mr. Roger Anderson Environmental Engineer State of New Mexico Oil Conservation Division 2040 S. Pacheco St. Santa Fe, New Mexico 87505

Subject: Change of Ownership

Dear Mr. Anderson:

The object of this letter is to advise the New Mexico Oil Conservation Division that effective December 29, 1994, ENRON / Northern Natural Gas Company has completed the sale of the following properties to GPM:

- 1. Hobbs Gas Plant
- 2. Hobbs Compressor Station #1
- 3. Hobbs Compressor Station #2
- 4. Hobbs Compressor Station #3
- 5. Hobbs Compressor Station #4
- 6. Hobbs Compressor Station #5
- 7. Eddy Compressor Station #1
- 8. Eddy Compressor Station #2
- 9. Eddy Compressor Station #3

Because of the change in ownership, GPM has assumed the responsibility for the following items which have been on-going between ENRON and the OCD:

1. Hobbs Gas Processing Plant

Oil/Water Separator - Former Liquid Waste Disposal Area: ENRON submitted drafts of the Remedial Design Report, Construction Specifications, and Drawings for OCD's review.

2. Hobbs Compressor Station #2

On October 7, 1994, OCD reviewed ENRON's report of "SUBSURFACE INVESTIGATION AT HOBBS COMPRESSOR STATION NO.2 AND HOBBS NATURAL GAS PROCESSING PLANT". OCD requested that six items of information be submitted to the OCD by January 31, 1995 (Copy enclosed). OCD's request was faxed to Vince Bernard of GPM on October 11, 1994, who agreed to respond to items #1, 5, and 6. ENRON's response to the remaining items is:





Mr. Roger Anderson January 10, 1994 Page No. 2

Item #2: The stockpiled soil at Hobbs Compressor Station #2 was disposed of in C. & C. Landfarm in Monument, New Mexico. The landfarm is owned by Jimmy Cooper.

Item #3: The purged groundwater at Hobbs Gas Plant was disposed of in the landfarm at the site. The water from Hobbs C.S. #2 has been arranged to be disposed of at the USPCI facility in Wenoka, Oklahoma. Because of the close of sale on December 28, 1994, the seven drums of water were moved from Hobbs C.S. #2 to ENRON's Eunice plant for temporary storage. USPCI has scheduled to pick the drum during the week of January 16, 1995. The disposal methods for the water were approved by Bill Olson (copy enclosed).

Item #4: The final dimensions of the excavations at Hobbs Compressor Station No. 2 are shown on the enclosed Figure 1.

The name and address of the GPM contact person is:

Vince Bernard, Director Safety & Environmental Affairs New Mexico Region GPM Gas Services Company 4044 Penbrook, Odessa, Texas 79762 Phone: (915) 368-1085 Fax: (915) 368 1170

Should you have any questions, please feel free to call me at (713) 646-7337.

Sincerely,

Mr. 3. Celu

Akhtar A. Alvi, P.E. Senior Environmental Engineer Environmental Affairs Department

CC: Vince Bernard, GPM, W/O Enclosure

State of New Mexico ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Santa Fe, New Mexico 87505



OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, New Mexico 87505

February 15, 1995

CERTIFIED MAIL RETURN RECEIPT NO. P-667-242-210

Vincent B. Bernard GPM Gas Corporation 4044 Penbrook Odessa, TX 79762

RE: CONTAMINATED SOIL DISPOSAL HOBBS #1, HOBBS #3 AND HOBBS #5 COMPRESSOR STATIONS LEA COUNTY, NEW MEXICO

Dear Mr. Bernard:

On December 7, 1994, the New Mexico Oil Conservation Division (OCD) received correspondence from ENRON Operations Company dated September 29, 1993 requesting to dispose of contaminated soils at either the C & C Landfarm or the OCD permitted landfarm at ENRON's Hobbs Gas Plant. The contaminated soils which are stockpiled at ENRON's Hobbs #1, Hobbs #3 and Hobbs #5 compressor stations were generated as a result of remedial actions. Since GPM Gas Corporation is currently the owner of these facilities, the OCD's response is directed to GPM.

The above referenced disposal request is approved under the following conditions:

- 1. GPM will analyze the soils from each station for TCLP chlorinated organics.
- 2. The results of the TCLP chlorinated organics analysis will be submitted to the OCD for approval prior to disposal of the soils.
- 3. All original documents will be submitted to the OCD Santa Fe Office with copies provided to the OCD Hobbs District Office.

VILLAGRA BUILDING - 403 Galisteo Forestry and Resources Conservation Division P.O. Box 1948 87504-1948 827-5830 Park and Recreation Division P.O. Box 1147 87504-1147 827-7465 2040 South Pacheco Office of the Secretary 827-5950 Administrative Services 827-5925 Energy Conservation & Management 827-5900 Mining and Minerals 827-5970 Oil Conservation 827-7131 Mr. Vincent B. Bernard February 15, 1995 Page 2

Please be advised that OCD approval of does not relieve GPM of liability should their operation result in actual pollution of surface or ground waters or the environment which may be actionable under other laws and/or regulations. In addition, OCD approval does not relieve GPM of responsibility for compliance with any other state, federal or local laws and/or regulations.

If you have any questions, please call me at (505) 827-7154.

Sincerely,

0

William C. Olson Hydrogeologist Environmental Bureau

xc: OCD Hobbs District Office

Fold at line over top of envelope right of the return address.	PS Form 38	J TOTAL Postage 0, & Fees postmark or Date	9 Peturn Receipt Showing to Whom, Date, & Address of Delivery	Return Receipt Showing	Restricted Delivery Fee	Special Delivery Fee	Certified Fee	Postage	P.O., State & ZIP Code	Street & No.	P 667 24 Certified A No Insurance C No not use for Build Same Sent to
of envelope to the turn address.		\$	╂					÷			LL7 군 나 큰 군 L ^[] Certified Mail Receipt No Insurance Coverage Provided Do not use for International Mail (See Reverse)



11525 West Carlsbad Highway, Hobbs, New Mexico 88240 (505) 393-5109 September 29, 1993

State of New Mexico Oil Conservation Division Mr. Bill Olsen Hydrogeologist P.O. Box 2088 Santa Fe, NM 87504



OIL CONSERVATION DIV. SANTA FE

Dear Mr. Olsen,

Enclosed you will find the final analysis from the bottom hole soil samples taken from Hobbs #1, Hobbs #5 and .Hobbs #3 UST sites. Further excavation is not possible due to the solid rock encountered at the bottom of the excavation sites. Soil excavated at these sites is currently be placed on plastic and covered with plastic until we can haul it to the land farm at the Hobbs Plant, or be given permission from your office for removal to C & C Land Farm for remediation. Clean backfill soil is being purchased to backfill the open excavations, and at this time we would like final closure at these sites. Please contact me if I can be of further assistance at (505)393-5109 ex 25.

Sincerely,

White Decce

Mike Kneese Environmental Field Technician

xc: Akhtar Alvi Lou Soldano Dennis Howell file w/attachments

									BS, NM 88240	
	LABOR			PHO INAL		4669 • 118 5 YSIS	REP		RMINGTON, NM	87401
					ANAL	_		ORI		
Cit.	Company: Address: y, State:	11525		ocessing lsbad Hwy 240	•	Date: Lab # :	9/28/93 H1795			
	ect Name:			k Removal						
Sa Ina	Location: mpled by: lyzed by: ple Type:	Hobbs MK MF Soil	#1	Date: Date:	9/19/93 9/20/93 Sample Con	Time: Time: ndition:	10:00 9:23 GIST		Units:	mg/kg
***	********* Field	*****	******	*******	******	********* ETHYL	********* PARA-	******** META-	******** ORTHO-	*****
*** 1000	********** Field Code	*****	******* TRPHC	********** BENZENE	********** TOLUENE	********* ETHYL BENZENE	********* PARA- XYLENE	********* META- XYLENE	********* ORTHO- XYLENE	*****
	Code 9319093-05		******* TRPHC 83.4	BENZENE	TOLUENE					*****
	Code 9319093-Us Oil Tank B 9319094-Ne	ottom w Oil		1	······	BENZENE	XYLENE	XYLENE	XYLENE	*****
	Code 9319093-Us Oil Tank B	ottom w Oil ttom	83.4	<0.001	<0.001	BENZENE <0.001	XYLENE <0.001	XYLENE <0.001	XYLENE <0.001	*****
2	Code 9319093-Us Oil Tank B 9319094-Ne Storage Bo	ottom w Oil ttom ycol ttom	83.4 3.4	<0.001 <0.001	<0.001 <0.001	BENZENE <0.001 <0.001	XYLENE <0.001 <0.001	XYLENE <0.001 <0.001	XYLENE <0.001 <0.001	*****

QC Recovery	435.2	1.004	0.865	0.978	0.956	0.958	0.993	l
QC Spike -	405.9	0.881	0.865	0.869	0.866	0.860	0.886	í.
Accuracy	107.2%	113.8%	100.0%	112.5%	110.4%	111.4%	112.1%	L
Air Blank	***	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	i.

Methods - GAS CHROMOTOGRAPHY; INFRARED SPECTROSCOPY - EPA SW-846; 8020, 418.1, 3540 OR 3510

e

Michael R. Fowler

7

-29-93 Date

I.

· ·			
		DUONE (015) 672,7001	
		PHONE (915) 673-7001 • 2111 BEE	CHWOOD . ABILENE, 1X 79603
	RATORIES	PHONE (505) 393-2326 • 101 E. M	ARLAND • HOBBS, NM 88240
	RATORIES	PHONE (505) 326-4669 • 118 S. COMMER	CIAL AVE. • FARMINGTON, NM 87401
		ANALYSIS REPORT	
Company: Address: City, State:	Enron Gas Processin 11525 W. Carlsbad H Hobbs, NM 88240	ng Date: Hwy. Lab #:	
Project Name: Location: Sampled by: Sample Type:	Hobbs #1 Tank Remov Hobbs #1 MK Soil	val Date: Sample Condition:	
Sample ID:	9319093 - Used Oil	Tank Bottom	
	TO	CLP INORGANICS (Leachate)	
PARAMETER		RESULT	<u>UNITS</u>
Silver Arsenic Barium Cadmium		<0.1 <0.1 2.0 <0.1	mg/L mg/L mg/L mg/L

<0.1 <0.1 <0.1

METHODS: TCLP INORGANICS (Leachate) - EPA 1311/7000


Michael R. Fowler

Chromium

Mercury Lead Selenium

> 9-29-93 Date

mg/L mg/L mg/L mg/L



<0.1

<0.1

TCLP INORGANICS (Leachate) - EPA 1311/7000 **METHODS:**

11

Michael R. Fowler

Lead

Selenium

こテータす

mğ/L

Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

	RATORIES	PHONE (505)	393-2326 ● 101 E. MA 9 ● 118 S. COMMERC	HWOOD • ABILENE, TX 79603 RLAND • HOBBS, NM 88240 IAL AVE. • FARMINGTON, NM 87401
Company: Address: City, State:	Enron Gas Processi 11525 W. Carlsbad Hobbs, NM 88240	ng Hwy.	Date: Lab # :	9/28/93 H1795-3
Project Name: Location: Sampled by: Sample Type:	Hobbs #1 Tank Remo Hobbs #1 MK Soil	Samp	Date: Date: Dle Condition:	9/19/93 GIST
Sample ID:	9319095 - Glycol S	torage Bottom		
	Т	CLP INORGANICS	(Leachate)	
<u>PARAMETER</u>		RESULT		<u>UNITS</u>
Silver Arsenic Barium Cadmium Chromium Mercury Lead Selenium		<0.1 <0.1 3.0 <0.1 <0.1 <0.1 <0.1 <0.1		mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L

L

Michael R. Fowler

-

9-29-93 Date

	ATORIES	PHONE (505) 39	3-2326 • 101 E. MA • 118 S. COMMERC	HWOOD • ABILENE, TX 79603 RLAND • HOBBS, NM 88240 IAL AVE. • FARMINGTON, NM 87401
Company: Address: City, State:	Enron Gas Processi 11525 W. Carlsbad Hobbs, NM 88240	ng Hwy.	Date: Lab # :	9/28/93 H1795-4
Project Name: Location: Sampled by: Sample Type:	Hobbs # 1 Tank Remo Hobbs # 1 MK Soil		Date: e Condition:	9/19/93 GIST
Sample ID:	9319096 - Pipeline	Liquid		
	T	CLP INORGANICS (Leachate)	
<u>PARAMETER</u>		RESULT		<u>UNITS</u>
Silver Arsenic Barium Cadmium Chromium Mercury Lead Selenium		<0.1 <0.1 1.0 <0.1 <0.1 <0.1 <0.1 <0.1		mg/L mg/L mg/L mg/L mg/L mg/L mg/L

Michael R. Fowler

4 , ;

> > <u>9-29-83</u> Date

			A 1						ENE, TX 79603	=
~					PHONE (50	5) 393-2326	0101 E. MAR	LAND HOBE	3S, NM 88240	
-	- LABOR	ATO	RIES	PHO	ONE (505) 326-	4669 🔹 118 S	. COMMERCIA	L AVE. • FAR	MINGTON, NM	87401
			F.	INAL	ANAL	YSIS	REP	ORT		
Cit	Company: Address: y, State:	11525	Gas Pro W. Car. , NM 88.	ocessing lsbad Hwy 240	•	Date: Lab # :	9/28/93 H1794			
Sa Ana	ect Name: Location: mpled by: lyzed by: ple Type:	Hobbs Hobbs MK MF Soil		k Removal Date: Date:	9/19/93 9/20/93 Sample Con	Time: Tíme: ndition:	9:45 9:13 GIST		Units:	mg/kg
**** Samp #	********** Field Code	*****	******* TRPHC	**************************************	TOLUENE	ETHYL BENZENE	********* PARA- XYLENE	********* META- XYLENE	********* ORTHO- XYLENE	*****
1	Used Glyco. #9319091	l-Btm	170.2	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
2	Used Oil-B #9319092	ottom	<1.0	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	

QC Recovery OC Spike	435.2 405.9		0.865		0.956		0.993
Accuracy Air Blank	107.2%	113.8%	100.0%	112.5% <0.001	110.4%	111.4%	112.18

Methods - GAS CHROMOTOGRAPHY; INFRARED SPECTROSCOPY - EPA SW-846; 8020, 418.1, 3540 OR 3510

Michael R. Fowler

2-22-93 Date L

ARD LABOR	ATORIES	PHONE (505) 393 PHONE (505) 326-4669	-2326 • 101 E. MAI	IWOOD • ABILENE, TX 79603 RLAND • HOBBS, NM 88240 AL AVE. • FARMINGTON, NM 87401
Address:	Enron Gas Processi 11525 W. Carlsbad Hobbs, NM 88240	ng Hwy.	Date: Lab #:	9/28/93 H1794-1
Project Name: Location: Sampled by: Sample Type:	Hobbs # 3 MK Soil	Sample	Date: Condition:	9/19/93 GIST
Sample 1D:	Hobbs 3 Used Glyco T	CLP INORGANICS (I	_	
PARAMETER		RESULT	·	<u>UNITS</u>
Silver Arsenic Barium Cadmium Chromium Mercury Lead Selenium		<0.1 <0.1 2.0 <0.1 <0.1 <0.1 <0.1 <0.1		mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L

NU

Michael R. Fowler

9-29-93 Date

	RATORIES	PHONE (505) 393-	2326 • 101 E. MA	HWOOD • ABILENE, TX 79603 RLAND • HOBBS, NM 88240 IAL AVE. • FARMINGTON, NM 87401
Company: Address: City, State:	Enron Gas Processi 11525 W. Carlsbad Hobbs, NM 88240	ing Hwy.	Date: Lab # :	9/28/93 H1794-2
Project Name: Location: Sampled by: Sample Type:	Hobbs #3 Tank Remo Hobbs #3 MK Soil	Sample	Date: Condition:	9/19/93 GIST
Sample ID:	Hobbs 3 Used Oil E	Bottom # 9319092		
	2	CLP INORGANICS (L	eachate)	
<u>PARAMETER</u>		<u>RESULT</u>		<u>UNITS</u>
Silver Arsenic Barium Cadmium Chromium Mercury Lead Selenium		<0.1 <0.1 2.0 <0.1 <0.1 <0.1 <0.1 <0.1		mg/L mg/L mg/L mg/L mg/L mg/L mg/L

(D

Michael R. Fowler

, 'e

9/29/93

Date

-							-			
					PHONE (91	5) 673-7001	2111 BEECH		ENE, TX 79603	
			AL					LAND • HOB		<u> </u>
										07404
		(AIO							MINGTON, NM	87401
			F.	INAL	ANAL	YSIS	REP	ORT		
Ci	Company: Address: ty, State:	11525	Gas Pr W. Car , NM 88	ocessing lsbad Hwy 240	•	Date: Lab #:	8/29/93 H1796			
S	ject Name: Location: ampled by: alyzed by:	Hobbs Hobbs MK MF	5 Pit (5	Date: Date:	9/19/93 9/20/93	Time: Time:	11:30 9:30			
Sa	mple Type:	Soil			Sample Con	ndition:	GIST		Units:	mg/kg
***	*******	*****	******	*******	******	*******	******	*****	*******	*****
Sam #	p Field Code		TRPHC	BENZENE	TOLUENE	ETHYL BENZENE	PARA- XYLENE	META- XYLENE	ORTHO- XYLENE	
1	9319097-Pi	peln	<1.0	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
2	Liquids Bo 9319098-Us Oil Bottom	ttom ed	325.8	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
	•			•	•	1				•

Methods - GAS CHROMOTOGRAPHY; INFRARED SPECTROSCOPY - EPA SW-846; 8020, 418.1, 3540 OR 3510

Michael R. Fowler

9-29-93

Date

*			
		PHONE (915) 673-7001 • 2111 BEI	ECHWOOD • ABILENE, TX 79603
	RATORIES	PHONE (505) 393-2326 • 101 E. I	MARLAND . HOBBS, NM 88240
	RATORIES	PHONE (505) 326-4669 • 118 S. COMME	RCIAL AVE. • FARMINGTON, NM 87401
		ANALYSIS REPORT	
Company: Address: City, State:	Enron Gas Processi 11525 W. Carlsbad Hobbs, NM 88240	ng Date Hwy. Lab #	
Project Name: Location: Sampled by: Sample Type:	Hobbs 5 Pit Closur Hobbs 5 MK Soil	e Date Sample Condition	
Sample ID:	9319097 - Pipeline	Liquids Bottom	
	T	CLP INORGANICS (Leachate)	
<u>PARAMETER</u>		RESULT	<u>UNITS</u>
Silver Arsenic Barium Cadmium Chromium		<0.1 0.2 1.0 <0.1 <0.1	mg/L mg/L mg/L mg/L mg/L

Michael R. Fowler

Mercury Lead Selenium

9-29-93 Date

mg/L mg/L

mg/L

		PHONE (915) 673-7001 • 2111 BEE	CHWOOD • ABILENE, TX 79603
	DINAL	PHONE (505) 393-2326 • 101 E. M	ARLAND . HOBBS, NM 88240
LABO	RATORIES	PHONE (505) 326-4669 • 118 S. COMMER	CIAL AVE. • FARMINGTON, NM 87401
	TCLP	ANALYSIS REPORT	
Company: Address: City, State:	Enron Gas Processi 11525 W. Carlsbad Hobbs, NM 88240	ng Date: Hwy. Lab # :	
Project Name: Location: Sampled by: Sample Type:	Hobbs 5 Pit Closur Hobbs 5 MK Soil	e Date: Sample Condition:	
Sample ID:	9319098 - Used Oil	Bottom	
	T	CLP INORGANICS (Leachate)	
<u>PARAMETER</u>		RESULT	<u>UNITS</u>
Silver Arsenic Barium Cadmium Chromium Mercury Lead Selenium		<0.1 0.1 0.9 <0.1 <0.1 <0.1 0.1	mg/L mg/L mg/L mg/L mg/L mg/L mg/L

METHODS: TCLP INORGANICS (Leachate) - EPA 1311/7000

1 1

Michael R. Fowler

Selenium

9-29-93 Date

mg'/L

STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

<u></u>DRUG FREE

BRUCE KING GOVERNOR

April 15, 1993

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE, NEW MEXICO 87504 (505) 827-5800

ANITA LOCKWOOD

CABINET SECRETARY CERTIFIED MAIL RETURN RECEIPT NO. P-667-242-337

Mr. Michael Kneese ENRON Gas Processing Company 11525 W. Carlsbad Highway Hobbs, New Mexico 88240

PIPELINE CONDENSATE TANK REMEDIATION RE: HOBBS COMPRESSOR STATIONS NO. 1, NO. 3 AND NO. 5 LEA COUNTY, NEW MEXICO

Dear Mr. Kneese:

The New Mexico Oil Conservation Division (OCD) is in the process of reviewing ENRON'S January 1993 "FORMER LIQUID PIPELINE CONDENSATE STORAGE SITE, HOBBS COMPRESSOR STATION NO. 1, FIELD INVESTIGATION REPORT" and ENRON'S January 1993 "FORMER LIQUID PIPELINE CONDENSATE STORAGE SITE, HOBBS COMPRESSOR STATION NO. 5, FIELD INVESTIGATION REPORT". These documents were hand delivered to OCD on March 10, 1993. The documents detail the results of ENRON's investigation of the extent of contamination resulting from the past use of below grade tanks at the Hobbs Compressor Station No. 1 and the Hobbs Compressor Station No. 5.

The reports appear to have adequately defined the extent of contamination related to the below grade tanks at the facilities. However, the OCD has the following comments and requests for additional information regarding the above referenced documents:

- The reports do not include the results of the final 1. contaminant levels upon completion of the excavation of contaminated soils. Please supply OCD with this information.
- According to the reports ENRON is considering options for 2. treatment/disposal of the contaminated soils excavated during the remediation projects. Please submit a proposal to OCD for treatment/disposal of these wastes.

(NOTE: Mainline natural gas compressor stations are not exempt RCRA Subtitle C Hazardous from Waste requirements. Subsequently, these soils must be tested, prior to treatment/disposal, to demonstrate that they do not exhibit hazardous waste characteristics.)

Mr. Michael Kneese April 15, 1993 Page 2

3. The reports do not include recommendations for final closure of the excavations. Please submit a plan for final closure.

Upon a review of the ENRON file it was noted that OCD is awaiting the final results of a hazardous waste characterization of contaminated soils from remedial activities at the Hobbs No. 3 compressor station. Please provide OCD with this information and a plan for final closure of the former below grade tanks sites which includes disposal or remediation of the contaminated soils.

Submission of the above information will allow OCD to complete a review of the remedial activities at the Hobbs No. 1, No. 3 and No. 5 compressor stations. If you have any questions, please contact me at (505) 827-5885.

Sincerely,

William C. Olson Hydrogeologist Environmental Bureau

xc: OCD Hobbs Office

RECEIVED

OCT 2 1 1992

OIL CONSERVATION DIV. SANTA FE

ENRON GAS PROCESSING COMPANY 11525 W. CARLSBAD HIGHWAY HOBBS, NEW MEXICO 88240 (505)393-5109

October 19, 1992

Mr. Roger Anderson Oil Conservation Division P.O. Box 2088 Santa Fe, New Mexico 87504

Dear Mr. Anderson:

This letter is to inform your Office that a pipeline condensate tank at our Hobbs #1 plant was replaced with a steel tank inside concrete containment. In the removal of this tank we discovered two abandoned fiberglass tanks which were buried directly North of the condensate tank. We also discovered contamination from the overfilling of the pipeline liquids tank during upsets in the 1970s. This was stopped in the early 1980s. Excavation of the contaminated site commenced. A hole approximately 150'x 75'x 30'deep was excavated, and sample results show a drastic reduction in the TPH levels. Enron Gas Processing in Houston made a decision to hire a

consulting/contracting firm out of Albuquerque, N.M. to determine the extent of the contamination, and determine what remedial action should be taken. IT Corp. will be contacting your office with the results of there findings. Attached you will find a copy of the results of our July sample. You will also receive a copy of our latest sample results as soon as I receive them from the lab.

If you may require any additional information, please contact me at 393-5109 ext.25

Sincerely Michael M. Kelo Michael Kneese Field Technician

xc: Jim Peterson w/attachments
 file

ASSA'	TAT TAT		
ANALYTICAL L. JOR Page 3 Receive	ANALYTICAL LORATORIES, INC. • 7300 Jefferson, N.E. • Albuquerque, New Mexico 87109 Page 3 Received: 07/31/92	lbuquerque, New Mexico 87109 REPORT Vork Order # 92-07-366 Results by Sample	te C • L - aso, Texas 79925
SAMPLE ID	E ID 3-086 N. OF EOIT	FRACTION <mark>01A</mark> TEST CODE <u>TMETAL</u> NAME <u>TCLP Met. Anal. in water</u> Date & Time Collected <u>07/30/92</u> Category <u>SOIL</u>	
	PARAMETER	RESULT LIMIT D_F DATE_EXT DATE_AWAL	
	Arsenic, As Barium, Ba Cadmium, Cd Chromium, Cr Lead, Pb Mercury, Hg Selenium, Se Silver, Ag	ND 0.0050 1.0 08/10/92 08/12/92 ND 0.050 1.0 08/10/92 08/13/92 0.0290 0.0030 1.0 08/10/92 08/13/92 0.030 0.0030 1.0 08/10/92 08/13/92 ND 0.020 1.0 08/10/92 08/12/92 ND 0.030 0.0020 1.0 08/10/92 08/12/92 ND 0.0020 1.0 08/10/92 08/12/92 08/12/92 ND 0.00020 1.0 08/110/92 08/112/92 08/112/92 ND 0.00020 1.0 0.8/113/92 08/112/92 08/112/92	٠
		Notes and Definitions for this Report:	
		ANALYST J <u>B</u> UNITS <u>mg/l</u> BATCH_ID <u>wgfaa-0074, wfaa-0040, wcvaa-0017</u> COMMENTS <u>rotal metal</u>	
			٠
Member. American Council of Independent Labor surrisa, Inc.	THIS REPORT MUST NO	THIS REPORT MUST NOT BE USED IN ANY MANNER BY THE CLIENT OR ANY OTHER THIRD PARTY TO CLAIM PRODUCT ENDORSEMENT BY THE NATIONAL LABORATORY VOLUNTARY ACCREDITATION PROGRAM OR ANY OTHER AGENCY OF THE UNITED STATES GOVERNMENT.	WVLAD