

1R - 228

**GENERAL  
CORRESPONDENCE**

**YEAR(S):**

2002

## Price, Wayne

---

**From:** Bob Allen [ballen@sesi-nm.com]  
**Sent:** Monday, February 04, 2002 8:30 AM  
**To:** 'Price, Wayne'  
**Subject:** RE: Saga Conoco State A Battery G-33-18s-38e



Site Photos.ppt

Wayne...please see attached photos...bob

-----Original Message-----

**From:** Price, Wayne [mailto:WPrice@state.nm.us]  
**Sent:** Friday, February 01, 2002 10:24 AM  
**To:** 'ballen@sesi-nm.com'  
**Subject:** Saga Conoco State A Battery G-33-18s-38e

Please provide photo of site



**Photo from SW Corner Looking NE**



**Photo of Drill Site**



**Photo of East Side of Site Looking North**

## **Price, Wayne**

---


**From:** Price, Wayne  
**Sent:** Friday, February 01, 2002 10:24 AM  
**To:** 'ballen@sesi-nm.com'  
**Subject:** Saga Conoco State A Battery G-33-18s-38e

**Contacts:** Bob Allen

Please provide photo of site

**Price, Wayne**

**From:** Jerri Lee [office@sesi-nm.com]  
**Sent:** Wednesday, January 30, 2002 2:31 PM  
**To:** Wayne Price  
**Subject:** Letter to OCD for Conoco State A

**Safety & Environmental Solutions, Inc.**

P.O. Box 1613  
703 E. Clinton Suite 102  
Hobbs, New Mexico 88240  
505/397-0510  
Fax 505/393-4388  
www.sesi-nm.com

January 22, 2002

Mr. Wayne Price  
Engineer  
New Mexico Oil Conservation Division  
1220 South St. Francis Drive  
Santa Fe, New Mexico 87505

Dear Wayne:

Enclosed please find the Assessment Report of the Conoco State A Battery located in Unit G of Section 33, Township 18 S Range 38 E, Lea County, New Mexico. This battery is active and currently being operated by Saga Petroleum LLC.

The work performed in October 2001 consisted of two (2) boreholes installed in the southwest corner of the battery. The results of the sampling indicate the vertical extent of contamination at the site to be 7' in borehole #1 and 13' in borehole #2. There was no indication that any contamination has migrated into the ground water in this area and no tests were conducted of the ground water.

Saga Petroleum LLC actively operates this battery and requests that no remedial action be required at this time. However, Saga does understand its responsibility for closure of the site upon abandonment.

If you have any questions, or I can be of further assistance please contact me at (505) 397-0510.

Sincerely,

1/30/2002

Bob Allen CHMM, REM, CET, CES  
President

enclosure

1/30/2002