


1R - 449

**GENERAL  
CORRESPONDENCE**

**YEAR(S):**

---



October 28, 2004

Mr. Paul Sheeley  
Oil Conservation Division – District 1  
New Mexico Energy, Minerals and Natural Resources Department  
1625 North French Drive  
Hobbs, New Mexico 88240

**Re: Final Pipeline Spill Investigation Report, Dynegy Midstream Services, L.P.,  
Unit Letter H (SE/4, NE/4), Section 19, Township 22 South, Range 38 East,  
Lea County, New Mexico**

Dear Mr. Sheeley:

Please find enclosed a copy of the above-referenced report. The report is submitted on behalf of Dynegy Midstream Services, L. P., and presents the final results of spill remediation conducted by Larson and Associates, Inc. Please call Dave Harris at (505) 394-2534 or myself at (432) 687-0901 if you have questions. I may also be reached by email at [Cindy@Laenvironmental.com](mailto:Cindy@Laenvironmental.com).

Sincerely,  
*Larson and Associates, Inc.*

Cindy K. Crain, PG

cc: Cal Wrangham – Dynegy  
Dave Harris - Dynegy  
Roger Holland - Dynegy

Dynergy Midstream Services, L. P.  
Eunice Plant Gathering System  
Closure Documentation Request Status as of July 12, 2005

Request Closure for Sites: 01, 02, 20, 05, 55, 06, 57, 64, 09, and 07.

Site No.	Name	Location	Action	Status
None	Hugh (Remediated)	NE/NW, Sec. 14, T22S, R37E	Completed	Completed
0-0100-01	Station #144-A	SE/NW, Sec. 1, T22S, R37E	Closure denied 8/11/04	Final report submitted requesting closure to NMOCD 12/10/04
0-0100-02	Station #144-B	SE/NW, Sec. 1, T22S, R37E	Further action complete.	Closure Approved 8/12/04
0-0100-50	Paddock "B"	NW/SE, Sec. 1, T22S, R37E	Report to NMOCD 1/23/04	Closure Approved 10/5/04
0-0100-49	Paddock "A"	NW/SE, Sec. 1, T22S, R37E	Report to NMOCD 1/23/04	-----
0-0100-08	Station 55 (6")	NW/SE, Sec. 12, T22S, R37E	Site Closed	-----
0-0100-20	Hugh 24"	NE/NW, Sec. 14, T22S, R37E	Report to NMOCD 12/10/04	Final report submitted requesting closure to NMOCD 12/10/04
0-0100-05	Gutman 24"	NE/SE, Sec. 24, T22S, R37E	Closure denied 8/12/04 Further action complete	Final report submitted requesting closure to NMOCD 5/10/05
0-0100-56	Flour 8"	SE/SW, Sec. 35, T22S, R37E	Report to NMOCD 1/23/04	Closure Approved 10/20/04
0-0100-55	Muncy	SE/NE, Sec. 19, T22S, R38E	Report to NMOCD 10/28/04	Final report submitted requesting closure to NMOCD 10/28/04
0-0100-03	Kennann Twin 8's	NW/SE, Sec. 30, T22S, R38E	Report to NMOCD 2/2/04	Closure Approved 8/12/04
0-0100-21	N. Vivian 13"	NE/NW, Sec. 30, T22S, R38E	Report to NMOCD 2/2/04	Closure Approved 8/12/04
0-0100-06	Vivian Battery	SE/NE, Sec. 30, T22S, R38E	Report to NMOCD 2/2/04	Final report submitted requesting closure to NMOCD 2/2/04
None	None	SW/SE, Sec. 3, T23S, R37E	No evidence of leak; not Dynergy line	-----
0-0100-57	Rattlesnake Draw	SE/NE, Sec. 11, T23S, R37E	Closure denied 8/12/04 Further action complete	Final report submitted requesting closure to NMOCD 1/25/05
0-0100-52	Hinton "B"	NE/SE, Sec. 12, T22S, R37E	Report to NMOCD 1/23/04	Closure Approved 8/12/04
0-0100-51	Hinton "A"	NE/SE, Sec. 12, T22S, R37E	Report to NMOCD 1/23/04	Closure Approved 10/8/04
0-0100-53	Turner Road Crossing	SE/SE, Sec. 20, T21S, R37E	Report to NMOCD 1/23/04	Closure Approved 8/12/04
0-0100-09	Graham 8" - A	SW/SW, Sec. 30, T21S, R37E	Report to NMOCD 11/21/03	Final report submitted requesting closure to NMOCD 11/21/03
0-0100-28	Graham 8" - B	SW/SW, Sec. 30, T21S, R37E	Report to NMOCD 12/10/03	Closure Approved 8/10/04
0-0100-58	Graham 8" - C	NE/NW, Sec. 30, T21S, R37E	Report to NMOCD 1/14/04	Closure Approved 8/12/04
0-0100-07	Station 60 (8")	SE/SW, Sec. 29, T21S, R37E	Report to NMOCD 8/18/04	Final report submitted requesting closure to NMOCD 8/18/04
0-0100-42	Kennann D. C. Hardy	SE/SE, Sec. 20, T21S, R37E	Report to DeLuca (only) 8/20/04	-----
0-0100-64	Hinton "14" #8	NW/SE, Sec. 20, T21S, R37E	Report to NMOCD 9/8/04	Final report submitted requesting closure to NMOCD 9/8/04