

2R - 48

**GENERAL
CORRESPONDENCE**

YEAR(S):
2002-2001

Price, Wayne

From: Dan Erskine [DErskine@maximusa.com]
Sent: Tuesday, February 05, 2002 12:02 PM
To: Price, Wayne; Clyde Yancey
Cc: Stubblefield, Mike; Dan Erskine; 'R-Neal.Goates@conoco.com'
Neal.Goates@conoco.com'

Subject: RE: Cedar Lake Draw Project 2R0048 Closure report

Here are project photos taken before and after remedial action. Sorry for the file size, the photos were not useful at lower resolution. Let me know if you need more info.

Thanks,
Dan

-----Original Message-----

From: Price, Wayne [mailto:WPrice@state.nm.us]
Sent: Wednesday, January 30, 2002 3:16 PM
To: 'Clyde Yancey'; Price, Wayne
Cc: Stubblefield, Mike; Dan Erskine; 'R-Neal.Goates@conoco.com'
Subject: RE: Cedar Lake Draw Project 2R0048 Closure report

Conoco's request for closure is hereby approved subject to the following conditions:

Please Provide photos via E-mail by 2/08/02.

Please be advised that NMOCD approval of this plan does not relieve Conoco of liability should their operations fail to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD approval does not relieve Conoco of responsibility for compliance with any other federal, state, or local laws and/or regulations.

-----Original Message-----

From: Clyde Yancey [mailto:CYancey@maximusa.com]
Sent: Wednesday, January 30, 2002 3:08 PM
To: 'Price, Wayne'
Cc: Stubblefield, Mike; Dan Erskine
Subject: RE: Cedar Lake Draw Project 2R0048 Closure report

Wayne

We do have some before pictures, and Dan Erskine indicated he will be in the area tomorrow and will take some photos for "after." We do not have any during photos.

Clyde

-----Original Message-----

From: Price, Wayne [mailto:WPrice@state.nm.us]
Sent: Wednesday, January 30, 2002 3:57 PM

2/6/2002

To: 'cyancey@maximusa.com'

Cc: Stubblefield, Mike

Subject: Cedar Lake Draw Project 2R0048 Closure report

Is there project photos available, before, during, after and a photo showing the site and cedar lake in background??

2/6/2002

Price, Wayne

From: Price, Wayne
Sent: Wednesday, January 30, 2002 3:16 PM
To: 'Clyde Yancey'; Price, Wayne
Cc: Stubblefield, Mike; Dan Erskine; 'R-Neal.Goates@conoco.com'
Neal.Goates@conoco.com'

Subject: RE: Cedar Lake Draw Project 2R0048 Closure report

Conoco's request for closure is hereby approved subject to the following conditions:

Please Provide photos via E-mail by 2/08/02.

Please be advised that NMOCD approval of this plan does not relieve Conoco of liability should their operations fail to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD approval does not relieve Conoco of responsibility for compliance with any other federal, state, or local laws and/or regulations.

-----Original Message-----

From: Clyde Yancey [mailto:CYancey@maximusa.com]
Sent: Wednesday, January 30, 2002 3:08 PM
To: 'Price, Wayne'
Cc: Stubblefield, Mike; Dan Erskine
Subject: RE: Cedar Lake Draw Project 2R0048 Closure report

Wayne

We do have some before pictures, and Dan Erskine indicated he will be in the area tomorrow and will take some photos for "after." We do not have any during photos.

Clyde

-----Original Message-----

From: Price, Wayne [mailto:WPrice@state.nm.us]
Sent: Wednesday, January 30, 2002 3:57 PM
To: 'cyancey@maximusa.com'
Cc: Stubblefield, Mike
Subject: Cedar Lake Draw Project 2R0048 Closure report

Is there project photos available, before, during, after and a photo showing the site and cedar lake in background??

1/30/2002

Price, Wayne

From: Price, Wayne
Sent: Wednesday, January 30, 2002 2:57 PM
To: 'cyancey@maximusa.com'
Cc: Stubblefield, Mike
Subject: Cedar Lake Draw Project 2R0048 Closure report

Contacts: Clyde Yancey

Is there project photos available, before, during, after and a photo showing the site and cedar lake in background??

E C L I

MAY 14 2001

May 7, 2001

CONSERVATION DIVISION

Mr. Wayne Price
NM Oil Conservation Division
2040 S. Pacheco
Santa Fe, NM 87505


RE: SOIL INVESTIGATION CEDAR LAKE DRAW, NEW MEXICO

Dear Mr. Price:

Accompanying this letter is a copy of a report detailing the subsurface investigation performed during January 24 and 25, 2001 and February 15, 2001 at the site of a release in the Skelly Gathering System pipeline near Cedar Lake Draw, New Mexico..

In the report we provide details of additional actions that we propose to implement at the facility. We are prepared to initiate these actions as soon as we receive your approval to proceed. If you have any questions or comments regarding this report, please do not hesitate to contact Clyde Yancey or Dan Erskine at 505-237-8440.


Sincerely,
MAXIM TECHNOLOGIES, INC.


Clyde L. Yancey, P.G.

ATTACHMENT

Date:
2/1/2002

Photographer:
D Erskine



1. Photograph facing east, taken after remedial action, with site features labeled.

Date:
2/15/2001

Photographer:
T. Tangen



2. Photograph taken before remedial action, facing south.

Cedar Lake Draw Remediation

Project #:
2007215

MAXIM Technologies, Inc.

Date:
Jan. 17, 2001

Photographer:
A. Stewart



3. Photograph taken before remedial action, facing north.

Date:
Jan. 17, 2001

Photographer:
A. Stewart



4. Photograph taken before remedial action, facing east.

Cedar Lake Draw
Remediation

Project #:
2007215

MAXIM Technologies, Inc.

Date:
Jan. 17, 2001

Photographer:
A. Stewart



5. Photograph taken before remedial action, facing west.

Date:
Jan. 17, 2001

Photographer:
A. Stewart



6. Photograph taken before remedial action, facing south.

Cedar Lake Draw
Remediation

Project #:
2007215

MAXIM Technologies, Inc.

Date:
2/1/2002

Photographer:
D Erskine



7. Looking west after remedial action.

Date:
2/1/2002

Photographer:
D Erskine



8. Looking northeast after remedial action.

Cedar Lake Draw
Remediation

Project #:
2007215

MAXIM Technologies, Inc.

Date:
2/1/2002

Photographer:
D Erskine



9. Looking east after remedial action.

Date:
2/1/2002

Photographer:
D Erskine



10. Looking northeast after remedial action.

Cedar Lake Draw Remediation

Project #:
2007215

MAXIM Technologies, Inc.