3R - <u>/7</u>

GENERAL CORRESPONDENCE

YEAR(S): Mar. 18, 1987



PER BAG STORE NO. NAME OIL CONSET VATION DU. DATE 3.30127 ADDRESS CITYPHONE						
CHECK BLACK AND FILM WHITE	FILM	FILM	FILM		OTHER	COLOR PRINT FROM SLIDES
DESDP & PRINT ORDERS REPRINT ORDERS FILM SIZE CL-ZU NO. OF ROLLS / ONE ROLL PER BAG NO. OF PRINTS FROM EACH NEG. NO. OF PRINTS / NO. OF PRINTS / DUPLICATE COLOR SLIDES DUPLICATE COLOR SLIDES						
	TRUCTION S3	ys P G			NTS DE DEV. PRINT TOTAL	- V [.]
Camera ge bankroom Santa FE • ALBUQUERQUE						



Augering at Amoco GCU # 153 E 3/18/87



Dehydrator & meter house at Amoco GCU # 153 E

3/18/87



Full drums of solvents (?) north of dehydration pit at Amore well GCU#153E

3/18/87



Produced water pit at Amoro well GCU#153E

3/18/87



Bloupit and empty drums on south edge of Amoco site Gen# 153 F

3/18/87



Overview of condensate tank, seperation unit and produced water pit at Amoco well GCU # 157E

3/18/87



Looking south Overview of separation upit, dehydration unit and location of full drams (solvents?) at Amoro well GCU #153 E

3/18/87

2 of 2



Overview poleny south of dehydrater and edicent pond at Anow well GCU # 153E

3/18/87

2 .f 2



Angoring to install monitor selling at Amoro well 6CU#153E

3/18/87