

**3R - 46**

**GENERAL  
CORRESPONDENCE**

**YEAR(S):  
1997**

# **BLAGG ENGINEERING, INC.**

P.O. Box 87, Bloomfield, New Mexico 87413

Phone: (505)632-1199 Fax: (505)632-3903

February 3, 1997

Mr. Roger Anderson  
Chief of Environmental Bureau  
State of New Mexico Oil Conservation Division  
2040 So. Pacheco  
Santa Fe, New Mexico 87505

**RE: Groundwater Impact**  
**Amoco Production Company: Sanchez GC C#1 - Blow pit**  
**Legal Description: Unit A, Sec. 28, T29N, R10W**  
**San Juan County, New Mexico**


Dear Mr. Anderson:

Initial groundwater sample analytical results at the above referenced well site during pit closure activity indicated contamination to be below the State of New Mexico Water Quality Control Commission's regulatory standards for benzene, toluene, ethylbenzene, and total xylenes (BTEX). Sampling on the Blow pit was conducted January 31, 1997. Depth to groundwater was measured at three (3) feet below grade. Listed below are summary analytical results for BTEX:

Parameter	Blow Pit (parts per billion)
Benzene	ND
Toluene	2.1
Ethylbenzene	1.6
Total Xylenes	16.0

If you have any questions concerning this information, please do not hesitate to contact us at (505) 632-1199. Thank you for your cooperation.

Respectfully submitted,  
**Blagg Engineering, Inc.**

  
Jeffrey C. Blagg, P.E.  
President

cc: Denny Foust, Deputy Oil & Gas Inspector, NMOCD, Aztec, NM  
Buddy Shaw, Environmental Coordinator, Amoco Production Company, Farmington, NM

NV/nv

SANCH-C1.LTR