

3R - 86

REPORTS

DATE:

2/19/1998



RECEIVED

FEB 23 1998

Environmental Bureau
Oil Conservation Division

Conoco Inc., Midland Division
Exploration and Production, North America
10 Desta Drive, Suite 100W
Midland, Texas 79705-4500

February 19, 1998

Attn.: Mr. Neal Goates, Senior Environmental Specialist

RE: Photographs of the Excavation Efforts at Farmington Com #1
Unit P, Sec 11, T29N, R13W

Per your request, Larry Trujillo of *On Site Technologies* took photographs of the Farmington Com #1 site before, during and after excavation efforts. Please find the attached copies of the photographs.

We hope that these photographs are satisfactory. If we can be of any further assistance, feel free to contact Myke Lane or myself at (505) 325-5667.

Thank you for your time and consideration.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Larry Trujillo", is written over a circular stamp or seal.

Larry Trujillo
Sr. Environmental Technician
On Site Technologies Limited Partnership

CC: Shirley Ebert, Field SHEAR Specialist,
Conoco Inc. Farmington office

Attachments
Copies of Com #1 photographs

PO Box 2606
Farmington, NM
505-325-5667 FAX: 505-327-1496

BEFORE EXCAVATION



BEFORE EXCAVATION



DURING EXCAVATION



DURING EXCAVATION



DURING EXCAVATION



DURING EXCAVATION



AFTER EXCAVATION



AFTER EXCAVATION

