

3R - ///

# GENERAL CORRESPONDENCE

YEAR(S):

2000

**BLAGG ENGINEERING, INC.**

P.O. Box 87, Bloomfield, New Mexico 87413  
Phone: (505) 632-1199 Fax: (505) 632-3903

JUN 29 2000

June 27, 2000

Mr. William C. Olson - Hydrologist  
State of New Mexico Oil Conservation Division  
2040 So. Pacheco  
Santa Fe, New Mexico 87505

**RE: Groundwater Impact  
Cross Timbers Oil Company:**

**Garcia GC B # 1 Well site  
Legal Description: Unit J, Sec. 21, T29N, R10W  
San Juan County, New Mexico**


Dear Mr. Anderson:

Initial groundwater sample analytical results at the above referenced well site from the production tank spill indicates contamination to be above the State of New Mexico Water Quality Control Commission's regulatory standards for benzene and total xylenes. The sample was collected from a monitor well (MW #4) installed by Envirotech, Inc. on April 26, 2000. Sampling of the monitor well was conducted April 27, 2000. Depth to water is estimated at approximately 40 feet below ground surface. Listed below are summary analytical results for benzene, toluene, ethylbenzene, and total xylenes (BTEX):

Parameter	Spill Cleanup (parts per billion)
benzene	63
toluene	120
ethylbenzene	130
Total xylenes	1540

If you have any questions concerning this information, please do not hesitate to contact us. Thank you for your cooperation.

Respectfully submitted,  
**Blagg Engineering, Inc.**

  
Jeffrey C. Blagg, P.E.  
President

cc: Denny Foust, Deputy Oil & Gas Inspector, NMOCD, Aztec, NM  
Nina Hutton, Environmental & Safety Manager, Cross Timbers Oil Company, Ft. Worth, TX

NV/nv

GARCIA.LTR