

3R - 112

APPROVALS

YEAR(S):

1999



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
2040 S. PACHECO
SANTA FE, NEW MEXICO 87505
(505) 827-7131

April 22, 1999

CERTIFIED MAIL
RETURN RECEIPT NO: Z-274-520-642

Ms. Nina Hutton
Cross Timbers Oil Company
810 Houston St., Suite 2000
Fort Worth, Texas 76102-6298

RE: PIT CLOSURE/GROUND WATER MONITORING REPORTS

Dear Ms. Hutton:

The New Mexico Oil Conservation Division (OCD) has reviewed Cross Timbers Oil Company's (CTOC) February 17, 1999 "CROSS TIMBERS OIL CO. (AMOCO) PIT CLOSURE/GROUNDWATER MONITORING REPORTS, SAN JUAN COUNTY, NEW MEXICO" which was submitted on behalf of CTOC by their consultant Blagg Engineering, Inc. This document contains the results of CTOC's investigation, remediation and monitoring of ground water contamination related to the disposal of oilfield wastes in unlined pits at 20 sites in the San Juan Basin and requests closure of the remedial actions.

Below is the OCD's review of the above referenced documents:

- A. The soil and ground water remedial actions at the sites listed below are satisfactory and the OCD **approves** of the closure of these pit sites. Please be advised that OCD approval does not relieve CTOC of liability if remaining contaminants pose a future threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve CTOC of responsibility for compliance with any other federal, state, tribal or local laws and regulations.

- | | |
|--|------------------------------|
| 1. Abrams GC C #1 (Blow pit) | Unit F, Sec. 25, T29N, R10W. |
| 2. Anderson GC A#1(Blow pit) | Unit C, Sec. 28, T29N, R10W. |
| 3. Armenta GC A#1 (Blow pit) | Unit D, Sec. 27, T29N, R10W. |
| 4. Baca GC A#1 (Blow pit) | Unit H, Sec. 26, T29N, R10W. |
| 5. Baca GC A#1 (Dehy pit) | Unit H, Sec. 26, T29N, R10W. |
| 6. Chavez GC C#1R (Blow/seperator pit) | Unit J, Sec. 23, T29N, R10W. |
| 7. Federal GC 3-1 (Blow pit) | Unit N, Sec. 23, T29N, R10W. |
| 8. Garcia GC B#1E (Blow pit) | Unit M, Sec. 21, T29N, R10W. |
| 9. Hare GC C#1 (Blow pit) | Unit M, Sec. 25, T29N, R10W. |
| 10. Hare GC C#1E (Blow pit) | Unit F, Sec. 25, T29N, R10W. |

- | | |
|--------------------------------------|------------------------------|
| 11. Hare GC F#1 (Separator pit) | Unit G, Sec. 23, T29N, R11W. |
| 12. Lefkovitz GC B#1 (Blow pit) | Unit A, Sec. 25, T29N, R10W. |
| 13. Lefkovitz GC B#1 (Separator pit) | Unit A, Sec. 25, T29N, R10W. |
| 14. Masden GC #1 (Separator pit) | Unit A, Sec. 28, T29N, R11W. |
| 15. Romero GC A#1 (Separator pit) | Unit K, Sec. 27, T29N, R10W. |
| 16. Stedje GC #1 (Blow pit) | Unit F, Sec. 27, T30N, R12W. |
| 17. Stedje GC #1E (Separator pit) | Unit A, Sec. 27, T30N, R12W. |
| 18. Trujillo GC A#1 (Blow pit) | Unit C, Sec. 28, T29N, R10W. |

B. The sites listed below have chloride and/or total dissolved solids (TDS) contamination of ground water in excess of New Mexico Water Quality Control Commission (WQCC) standards. In addition, the downgradient and/or lateral extent of chloride and/or TDS contamination in ground water at these sites has not been completely defined. Therefore, approval of the closure actions at these sites is **denied**. The OCD requires that CTOC investigate the extent of and remediate these contaminants at each site pursuant to the previously approved ground water management plan.

- | | |
|---------------------------------------|------------------------------|
| 1. Baca GC A #1A (Blow/separator pit) | Unit F, Sec. 26, T29N, R10W. |
| 2. Haney GC B#1E (Separator pit) | Unit M, Sec. 20, T29N, R10W. |

If you have any questions, please contact me at (505) 827-7154.

Sincerely,



William C. Olson
Hydrologist
Environmental Bureau

xc: Denny Foust, OCD Aztec District Office
Bill Liess, BLM Farmington District Office
Nelson Velez, Blagg Engineering, Inc.