3R - 155

REPORTS

DATE: 2001-1997



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

July 18, 2001

CERTIFIED MAIL RETURN RECEIPT NO. 3771-7460

Mr. Scott T. Pope El Paso Field Services 614 Reilly Ave. Farmington, New Mexico

87401

RE: 2000 SAN JUAN BASIN ANNUAL GROUNDWATER REPORT

Dear Mr. Pope:

The New Mexico Oil Conservation Division (OCD) has reviewed El Paso Field Services (EPFS) February 26, 2001 "2000 PIT PROJECT ANNUAL GROUNDWATER REPORT". This document contains the results of EPFS's 2000 monitoring and remediation of contaminated ground water related to the closure of unlined oil and gas production pits at 36 sites in the San Juan Basin. The documents also requests closure for 6 of the sites based on the remediation and monitoring actions taken to date.

The OCD's review of the above referenced document is addressed below:

A. Final pit closure approvals for the sites listed below were previously issued by the OCD on April 3, 2001.

1.	Charlie Pah #2 (Drip pit)	Unit B, Sec. 12, T27N, R09W
2.	K-51 Line Drip (Drip pit)	Unit A, Sec. 34, T26N, R06W
3.	Mesa CPD (Drip pit)	Unit E, Sec. 04, T29N, R14W
4.	Sheets Well #2 (Drip pit)	Unit H, Sec. 28, T31N, R09W
5.	Turner A#1 Pit #1 (Dehy pit)	Unit K, Sec. 34, T31N, R11W
6.	Turner A#1 Pit #2 (Drip pit)	Unit K, Sec. 34, T31N, R11W

Mr. Scott T. Pope July 18, 2001 Page 2

B. The final pit closure and ground water activities at the sites listed below appear satisfactory. However, the reports do not include a completed pit remediation and closure form which contains the results of all soil remediation actions. The OCD cannot issue final closure approval until EPFS submits this information.

Ohio C Government #3 (Dehy pit)
 Unit P, Sec. 26, T28N, R11W
 Anderson GC A#1 (CH) (Dehy pit)
 Unit C, Sec. 28, T29N, R10W.

C. A review of the annual ground water reports for the sites listed below shows that the extent of ground water contamination in excess of WQCC standards at these sites has not been defined or the sites do not contain permanent downgradient ground water monitoring points. The OCD requires that EPFS install additional ground water monitoring wells at these sites to monitor and determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.

1.	Hammond #41A	Unit O, Sec. 25, T27N, R08W
2.	James F Bell #1E	Unit P, Sec. 10, T30N, R13W
3.	K-27 Line Drip	Unit E, Sec. 04, T25N, R06W
4.	K-31 Line Drip	Unit N, Sec. 16, T25N, R06W
5.	Lateral 0-21 Line Drip	Unit O, Sec. 12, T30N, R09W
6.	Lindrith B#24	Unit N, Sec. 09, T24N, R03W
7.	Miles Federal #1A (CH)	Unit F, Sec. 05, T26N, R07W
8.	State Gas Com N#1	Unit H. Sec. 16, T31N, R12W

D. At the sites listed below where EPFS states that there is possible ground water contamination related to the operators activities, the OCD requests that EPFS work cooperatively with the operator to investigate and remediate contaminated ground water.

1.	Canada Mesa #2	Unit I, Sec. 24, T24N, R06W
2.	Fields A #7A	Unit E, Sec. 34, T32N, R11W
3.	Fogelson 4-1 Com #14	Unit P, Sec. 04, T29N, R11W
4.	Gallegos Canyon Unit Com A #142E	Unit G, Sec. 25, T29N, R12W
5.	Johnston Federal #4	Unit H, Sec. 33, T31N, R09W
6.	Johnston Federal #6A	Unit F, Sec. 35, T31N, R09W
7.	Knight #1	Unit A, Sec. 05, T30N, R13W
8.	Sandoval Gas Com A #1A	Unit C, Sec. 35, T30N, R09W
9.	Standard Oil Com #1	Unit N, Sec. 36, T29N, R09W

Mr. Scott T. Pope July 18, 2001 Page 3

If you have any questions, please call me at (505) 476-3491.

Sincerely,

William C. Olson

Hydrologist

Environmental Bureau

xc: Denny Foust, OCD Aztec District Office

Bill Liess, BLM Farmington District Office

Mike Matush, NM State Land Office Bill Freeman, Navajo Nation EPA

STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION 2040 S. PACHECO SANTA FE, NEW MEXICO 87505 (505) 827-7131

July 8, 1998

CERTIFIED MAIL RETURN RECEIPT NO. Z-235-437-304

Ms. Sandra D. Miller El Paso Field Services 614 Reilly Ave. Farmington, New Mexico

87401

RE: SAN JUAN BASIN ANNUAL GROUNDWATER REPORT

Dear Ms. Miller:

The New Mexico Oil Conservation Division (OCD) has completed a review of El Paso Field Services (EPFS) February 27, 1998 "RE: 1997 GROUNDWATER ANNUAL REPORT" and accompanying March 1998 "SAN JUAN BASIN PIT CLOSURES, SAN JUAN BASIN, NEW MEXICO, EL FIELD SERVICES PIT PROJECT PIT CLOSURE REPORT" and March 1998 "SAN JUAN BASIN PIT CLOSURE, SAN JUAN BASIN, NEW MEXICO, EL PASO FIELD SERVICES PIT PROJECT GROUNDWATER REPORT ANNUAL REPORT". These documents contain the results of EPFS's 1997 monitoring and remediation of contaminated ground water related to the closure of unlined oil and gas production pits at 57 sites in the San Juan Basin. The documents also requests closure for 11 of the sites based on the remediation and monitoring actions taken to date.

The OCD's review of the above referenced documents is addressed below:

A. The final pit closure, soil remediation and ground water activities conducted at the 10 sites listed below are approved and the OCD considers these sites closed.

1.	2C-45 Line Drip (Drip pit)	Unit P, Sec. 06, T25N, R13W
2.	Miles Federal #1A (MV) (Drip pit)	Unit F, Sec. 05, T26N, R07W
3.	Graham #53 (Dehy pit)	Unit L, Sec. 10, T27N, R08W
4.	K-17 Line Drip (Drip pit)	Unit C, Sec. 26, T27N, R08W
5.	John Charles #8 (Dehy pit)	Unit B, Sec. 13, T27N, R09W
6.	Florance C LS #7 (Drip pit)	Unit F, Sec. 30, T28N, R08W
7:	Trunk D Line Drip (Drip pit)	Unit F, Sec. 20, T28N, R08W
8.	Trujillo GC #1 PC (Drip pit)	Unit M, Sec. 21, T29N, R10W
9.	Usselman Gas Com #1 (Drip pit)	Unit B, Sec. 04, T31N, R10W
10.	Lat H-37 Drip Y-3 (Line drip pit)	Unit F, Sec. 01, T31N, R13W

Ms. Sandra D. Miller July 8, 1998 Page 2

Please be advised that OCD approval does not relieve EPFS of liability if remaining contaminants are found to pose a future threat to surface water, ground water, human health or the environment. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state or local laws and regulations.

- B. The closure report for the site listed below shows that ground waters in a piezometer downgradient from the source area at the pit are still contaminated in excess of New Mexico Water Quality Control Commission (WQCC) ground water standards. In addition a review of the data shows that the downgradient extent of contamination has not been completely defined. Therefore, the OCD cannot issue final closure approval at this time and approval of closure actions at this site is denied. The OCD requires that EPFS install additional ground water monitoring wells to monitor and determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.
 - 1 Sheets #2 (Drip pit)

17.

State Gas Com N#1

Unit H, Sec. 28, T31N, R09W.

Unit H, Sec. 16, T31N, R12W

- C. A review of the annual ground water reports for the sites listed below shows that the extent of ground water contamination in excess of WQCC standards at these sites has not been defined or the sites do not contain permanent downgradient ground water monitoring points. The OCD requires that EPFS install additional ground water monitoring wells at these sites to monitor and determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.
 - Unit C, Sec. 28, T29N, R10W Anderson GC A#1 CH 1. 2. D Loop Line Drip Unit I, Sec. 33, T28N, R08W 3. Hammond #41A Unit O, Sec. 25, T27N, R08W Unit H, Sec. 28, T31N, R09W 4. Horton #1E 5. James F Bell #1E Unit P, Sec. 10, T30N, R13W 6. Jennapah #1 Unit H, Sec. 36, T28N, R09W 7. Unit E, Sec. 04, T25N, R06W K-27 Line Drip 8. Unit N, Sec. 16, T25N, R06W K-31 Line Drip 9. Lat 3B-39 Line Drip Unit M, Sec. 10, T29N, R09W 10. Lat L-40 Line Drip Unit H, Sec. 13, T28N, R04W 11. Lateral 0-21 Line Drip Unit O, Sec. 12, T30N, R09W 12. Lindrith B#24 Unit N, Sec. 09, T24N, R03W 13. K-27 Line Drip Unit E, Sec. 04, T25N, R06W 14. Mesa CPD Unit C, Sec. 04, T29N, R14W 15. Miles Federal #1A (CH) Unit F, Sec. 05, T26N, R07W 16. Ramenta Et Al #1 Unit J, Sec. 13, T27N, R09W

Ms. Sandra D. Miller July 8, 1998 Page 3

D. At the sites listed below EPS proposes to take no further actions until the operator commences remediation associated with their production pits. The OCD is sending letters to the operators of these sites requiring them to investigate and remediate soil and ground water contamination related to their activities. The OCD requests that EPFS work cooperatively with the operator to investigate and remediate contaminated ground water at these sites.

		·
1.	Canada Mesa #2	Unit I, Sec. 24, T24N, R06W
2.	Coldiron Com A #1	Unit K, Sec. 02, T30N, R11W
3.	Fields A #7A	Unit E, Sec. 34, T32N, R11W
4.	Fogelson 4-1 Com #14	Unit P, Sec. 04, T29N, R11W
5.	Gallegos Canyon Unit Com A #142E	Unit G, Sec. 25, T29N, R12W
6.	Johnston Federal #4	Unit H, Sec. 33, T31N, R09W
7.	Johnston Federal #6A	Unit F, Sec. 35, T31N, R09W
8.	Knight #1	Unit A, Sec. 05, T30N, R13W
9.	Ohio C Govt #3	Unit P, Sec. 26, T28N, R11W
10.	Sandoval Gas Com A #1A	Unit C, Sec. 35, T30N, R09W
11.	Standard Oil Com #1	Unit N, Sec. 36, T29N, R09W
12.	Turner A #1	Unit K, Sec. 34, T31N, R11W

If you have any questions, please call me at (505) 827-7154.

Sincerely,

William C. Olson

Hydrologist

Environmental Bureau

xc: Denny Foust, OCD Aztec District Office
Bill Liess, BLM Farmington District Office

Mike Matush, New Mexico State Land Office





ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO SANTA FE, NEW MEXICO 87505 (505) 827-7131

August 6, 1997

CERTIFIED MAIL RETURN RECEIPT NO. P-410-431-203

Mr. Ricky D. Cosby El Paso Field Services P.O. Box 4990 Farmington, New Mexico

87499

RE: SAN JUAN BASIN GROUND WATER REPORTS

Dear Mr. Cosby:

The New Mexico Oil Conservation Division (OCD) has reviewed El Paso Field Service's (EPFS) June 2, 1997 "SEMI-ANNUAL EL PASO FIELD SERVICES PIT PROJECT GROUND WATER REPORT". This document contains EPFS's a listing of San Juan Basin pit closure sites at which EPFS has encountered ground water and a proposal to modify the reporting schedule for ground water cases from semi-annual to annual.

The above referenced proposal is approved with the following conditions:

- 1. EPFS will submit the annual reports on investigation/remedial activities to the OCD by December 1 of each respective year. The reports will present the information on each site as a separate case. Each case will contain:
 - a. A description of all investigation remediation activities which occurred during the past year including conclusions and recommendations.
 - b. Summary tables of all past and present laboratory analytic results of ground water quality monitoring including copies of the past years laboratory data sheets and associated quality assurance/quality control data.

Mr. Ricky Cosby August 6, 1997 Page 2

- A site map and a quarterly water table elevation map using the water table elevation C. of the ground water in all monitor wells.
- d. A geologic log and completion diagram for each monitor well.
- The disposition of all wastes generated.
- f. Isoconcentration maps for contaminants of concern at the site (ie. benzene, BTEX, chloride, TDS, etc.).

Please be advised that OCD approval does not relieve EPFS of liability if contamination exists which is beyond the scope of the work plan; if the activities fail to adequately determine the extent of contamination; or if the activities fail to adequately remediate or monitor contamination related to EPFS's activities. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state or local laws and/or regulations.

If you have any questions, please call me at (505) 827-7154.

Sincerely,

William C. Olson

Hydrogeologist

Environmental Bureau

Denny Foust, OCD Aztec District Office XC:

Bill Liess, BLM Farmington District