3R - /79


GENERAL CORRESPONDENCE

YEAR(S): 2000 - 1998

3

Groundwater Site Map





11 COMPERVATION DIVINITY

Certified Mail: #Z 213 707 662

February 17, 2000

Mr. William C. Olson New Mexico Oil Conservation Division 2040 S. Pacheco Santa Fe, NM 87504

RE: Corrected Request for Extension for 2000 Pit Project Annual Groundwater Report

Dear Mr. Olson:

Please except this request for extension with the dates corrected to reflect the current year.

The pit project annual groundwater report is due to you on March 1, 2000. Pursuant to our February 8, 2000 telephone conversation, El Paso Field Services (EPFS) hereby requests a one-month extension to the submittal date. EPFS will submit the pit project annual report to your office by April 3, 2000.

If you have any questions or require any additional information, please contact me at (505) 599-2124.

Sincerely,

Scott T. Pope P.G.

Environmental Scientist

xc: Mr. Denny Foust, NMOCD - Aztec



Certified Mail: #Z 387 666 326

February 8, 1999

Mr. William C. Olson New Mexico Oil Conservation Division 2040 S. Pacheco Santa Fe, NM 87504

RE: 2000 Pit Project Annual Groundwater Report

Dear Mr. Olson:

The pit project annual groundwater report is due to you on March 1, 1999. Pursuant to our February 8, 1999 telephone conversation, El Paso Field Services (EPFS) hereby requests a one-month extension to the submittal date. EPFS will submit the pit project annual report to your office by April 3, 1999.

If you have any questions or require any additional information, please contact me at (505) 599-2124.

Sincerely,

Scott T. Pope P.G.

Environmental Scientist

xc: Mr. Denny Foust, NMOCD - Aztec

SELLY SELLY

STATE OF NEW MEXICO

ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO SANTA FE. NEW MEXICO 87505 (505) 827-7131

July 9, 1998

CERTIFIED MAIL RETURN RECEIPT NO. Z-235-437-308

Mr. B.D. Shaw Amoco Production Company 200 Amoco Court Farmington, New Mexico 87401

RE: SAN JUAN BASIN PIT GROUND WATER SITES

Dear Mr. Shaw:

Information in El Paso Field Services (EPFS) recent annual ground water monitoring report shows the presence of shallow ground at some well sites operated by Amoco Production Company (Amoco). Disposal activities at EPFS pits on these locations have resulted in contamination of shallow ground water. These sites also apparently have former unlined production pits operated by Amoco, some of which appear to be contributing to ground water contamination seen in EPFS monitoring wells.

Due to the presence of ground water contamination at these sites and the apparent commingling of contaminated waters from EPFS's former unlined dehy pit and Amoco's former unlined production pits, the OCD requests that Amoco cooperate with EPFS to investigate and remediate contaminated ground water at the sites listed below:

| 1. | Coldiron Com A#1 | Unit K, Sec. 02, T30N, R11W. |
|----|----------------------------------|------------------------------|
| 2. | Fields A #7A | Unit E, Sec. 34, T32N, R11W. |
| 3. | Gallegos Canyon Unit Com A #142E | Unit G, Sec. 25, T29N, R12W. |
| 4. | Sandoval Gas Com A #1A | Unit C. Sec. 35, T30N, R09W. |

If you have any questions, please contact me at (505) 827-7154.

Sincerely

William C. Olson

Hydrologist

Environmental Bureau

XC:

Denny Foust, OCD Aztec District Office Sandra D. Miller, El Paso Field Services Bill Liess, BLM Farmington Office