

3R - 240

**APPROVALS**

**YEAR(S):**

1999-1997



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO  
SANTA FE, NEW MEXICO 87505  
(505) 827-7131

July 28, 1999

**CERTIFIED MAIL**  
**RETURN RECEIPT NO. Z-274-520-686**

Mr. Scott T. Pope  
El Paso Field Services  
614 Reilly Ave.  
Farmington, New Mexico 87401

**RE: SAN JUAN BASIN ANNUAL GROUNDWATER REPORT**

Dear Mr. Pope:

The New Mexico Oil Conservation Division (OCD) has completed a review of El Paso Field Services (EPFS) March 31, 1999 "1998 GROUNDWATER ANNUAL REPORT". This document contains the results of EPFS's 1998 monitoring and remediation of contaminated ground water related to the closure of unlined oil and gas production pits at 49 sites in the San Juan Basin. The documents also requests closure for 18 of the sites based on the remediation and monitoring actions taken to date.

The OCD's review of the above referenced document is addressed below:

A. The final pit closure, soil remediation and ground water activities conducted at the sites listed below are **approved**.

- |     |                                       |                             |
|-----|---------------------------------------|-----------------------------|
| 1.  | 2C-22 #3 Line Drip (Drip pit)         | Unit G, Sec. 13, T24N, R06W |
| 2.  | Candado #23 MV/CH (Drip pit)          | Unit B, Sec. 09, T26N, R07W |
| 3.  | Canyon Largo Unit #304 (Drip pit)     | Unit C, Sec. 11, T24N, R06W |
| 4.  | De Na Haz Za #1 (Drip pit)            | Unit D, Sec. 18, T26N, R08W |
| 5.  | Florance #1 (Drip pit)                | Unit J, Sec. 08, T30N, R11W |
| 6.  | Gallegos Canyon Unit D#160 (Dehy pit) | Unit I, Sec. 27, T29N, R12W |
| 7.  | Harrington #1 (Drip pit)              | Unit M, Sec. 31, T27N, R07W |
| 8.  | Johnson #1E (Dehy pit)                | Unit P, Sec. 21, T31N, R13W |
| 9.  | Miles Federal #1E (Dehy pit)          | Unit N, Sec. 05, T26N, R07W |
| 10. | Nickles #1 (Dehy pit)                 | Unit K, Sec. 11, T31N, R13W |
| 11. | Sanchez Gas Com B#1 (Dehy pit)        | Unit G, Sec. 28, T29N, R10W |
| 12. | San Juan 28-6 #79 (Dehy pit)          | Unit M, Sec. 11, T27N, R06W |
| 13. | Trujillo Gas Com A#1 (Drip pit)       | Unit C, Sec. 28, T29N, R10W |
| 14. | Trunk 2B Drip X-1 (Drip pit)          | Unit J, Sec. 01, T27N, R11W |
| 15. | Valdez Gas Unit A#1E (CH) (Drip pit)  | Unit G, Sec. 24, T29N, R11W |

Please be advised that OCD approval does not relieve EPFS of liability if remaining contaminants are found to pose a future threat to surface water, ground water, human health or the environment. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state, local or tribal laws and regulations.

- B. The closure reports for the sites listed below show that ground waters downgradient from the pit source areas are contaminated in excess of New Mexico Water Quality Control Commission (WQCC) ground water standards and/or the downgradient extent of contamination has not been completely defined. Therefore, the OCD cannot issue final closure approval at this time and approval of closure actions at this site is **denied**. The OCD requires that EPFS install additional ground water monitoring wells to monitor and/or determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.

- |    |   |                             |
|----|---|-----------------------------|
| 1. | Anderson GC A#1 CH (Drip pit)             | Unit C, Sec. 28, T29N, R10W |
| 2. | Mesa CPD (Drip pit)                       | Unit E, Sec. 04, T29N, R14W |
| 3. | Ohio "C" Government #3 (Drip & dehy pits) | Unit P, Sec. 26, T28N, R11W |

- C. A review of the reports for the sites listed below shows that the extent of ground water contamination in excess of WQCC standards is not defined or the sites do not contain permanent downgradient ground water monitoring points. On July 8, 1998 the OCD required that EPFS install additional ground water monitoring wells at these sites to monitor and determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan. To date this work has not been conducted. The OCD requires that EPFS install additional ground water monitoring wells at these sites, by December 31, 1999.

- |     |                        |                             |
|-----|------------------------|-----------------------------|
| 1.  | D Loop Line Drip       | Unit I, Sec. 33, T28N, R08W |
| 2.  | Hammond #41A           | Unit O, Sec. 25, T27N, R08W |
| 3.  | Hamner #9              | Unit A, Sec. 20, T29N, R09W |
| 4.  | Horton #1E             | Unit H, Sec. 28, T31N, R09W |
| 5.  | James F Bell #1E       | Unit P, Sec. 10, T30N, R13W |
| 6.  | Jennapah #1            | Unit H, Sec. 36, T28N, R09W |
| 7.  | K-27 Line Drip         | Unit E, Sec. 04, T25N, R06W |
| 8.  | K-31 Line Drip         | Unit N, Sec. 16, T25N, R06W |
| 9.  | Lat 3B-39 Line Drip    | Unit M, Sec. 10, T29N, R09W |
| 10. | Lat L-40 Line Drip     | Unit H, Sec. 13, T28N, R04W |
| 11. | Lateral 0-21 Line Drip | Unit O, Sec. 12, T30N, R09W |
| 12. | Lindrith B#24          | Unit N, Sec. 09, T24N, R03W |
| 13. | Miles Federal #1A (CH) | Unit F, Sec. 05, T26N, R07W |
| 14. | Ramenta Et Al #1       | Unit J, Sec. 13, T27N, R09W |
| 15. | Sheets #2              | Unit H, Sec. 28, T31N, R09W |
| 16. | State Gas Com N#1      | Unit H, Sec. 16, T31N, R12W |

- D. At the site listed below EPS proposes to take no further actions until the operator commences remediation associated with their production pit. Burlington Resources (BR), the operator of the production pit, recently investigated and remediated contaminated soils at their pit and installed a monitor well to determine ground water quality beneath the pit. The results of this work showed that at the base of BR's excavation (38 feet) that there was no detectable benzene, toluene, ethylbenzene and xylene (BTEX) or total petroleum hydrocarbons in the remaining soil. In addition, BR's monitor well installed at the pit showed that there was only 0.5 ppb of xylene was in ground water beneath the pit. Based upon these results and the results of EPFS's investigations, it appears that EPFS's pit is the source of ground water contamination at the site. Therefore, the OCD requires that EPFS install additional ground water monitoring wells to determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.

1. Johnston Federal #6A

Unit F, Sec. 35, T31N, R09W

- E. The report for the site Turner A#1 states that EPFS is working with the operator of the well site on the site remedial actions. EPFS lists the operator of the site as BR. BR has informed the OCD that BR has no operations in the vicinity of EPFS's dehy unit for this site and that the area where EPFS found impacted ground water is actually on an Amoco location where the gas from the Turner A#1 is measured. Please clarify who is the well operator at the location of EPFS's Turner A#1 dehy unit.

If you have any questions, please call me at (505) 827-7154.

Sincerely,



William C. Olson  
Hydrologist  
Environmental Bureau

xc: Denny Foust, OCD Aztec District Office  
Bill Liess, BLM Farmington District Office  
Mike Matush, New Mexico State Land Office  
Charmaine Hosteen, Navajo EPA



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
2040 S. PACHECO  
SANTA FE, NEW MEXICO 87505  
(505) 827-7131

August 6, 1997

**CERTIFIED MAIL**  
**RETURN RECEIPT NO. P-410-431-203**

Mr. Ricky D. Cosby  
El Paso Field Services  
P.O. Box 4990  
Farmington, New Mexico 87499

**RE: SAN JUAN BASIN GROUND WATER REPORTS**

Dear Mr. Cosby:

The New Mexico Oil Conservation Division (OCD) has reviewed El Paso Field Service's (EPFS) June 2, 1997 "SEMI-ANNUAL EL PASO FIELD SERVICES PIT PROJECT GROUND WATER REPORT". This document contains EPFS's a listing of San Juan Basin pit closure sites at which EPFS has encountered ground water and a proposal to modify the reporting schedule for ground water cases from semi-annual to annual.

The above referenced proposal is approved with the following conditions:

1. EPFS will submit the annual reports on investigation/remedial activities to the OCD by December 1 of each respective year. The reports will present the information on each site as a separate case. Each case will contain:
  - a. A description of all investigation remediation activities which occurred during the past year including conclusions and recommendations.
  - b. Summary tables of all past and present laboratory analytic results of ground water quality monitoring including copies of the past years laboratory data sheets and associated quality assurance/quality control data.

Mr. Ricky Cosby

August 6, 1997

Page 2

- c. A site map and a quarterly water table elevation map using the water table elevation of the ground water in all monitor wells.
- d. A geologic log and completion diagram for each monitor well.
- e. The disposition of all wastes generated.
- f. Isoconcentration maps for contaminants of concern at the site (ie. benzene, BTEX, chloride, TDS, etc.).

Please be advised that OCD approval does not relieve EPFS of liability if contamination exists which is beyond the scope of the work plan; if the activities fail to adequately determine the extent of contamination; or if the activities fail to adequately remediate or monitor contamination related to EPFS's activities. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state or local laws and/or regulations.

If you have any questions, please call me at (505) 827-7154.

Sincerely,



William C. Olson  
Hydrogeologist  
Environmental Bureau

xc: Denny Foust, OCD Aztec District Office  
Bill Liess, BLM Farmington District



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO  
SANTA FE, NEW MEXICO 87505  
(505) 827-7131

January 24, 1997

**CERTIFIED MAIL**

**RETURN RECEIPT NO. P-269-269-241**

Ms. Sandra Miller  
El Paso Field Services  
P.O. Box 4990  
Farmington, New Mexico 87499

**RE: FINAL SAN JUAN BASIN PIT CLOSURE REPORTS**

Dear Ms. Miler:

The New Mexico Oil Conservation Division (OCD) has completed a review of El Paso Field Services (EPFS) August 20, 1996 "PRODUCTION PIT CLOSURE SUBMITTAL" and July 1996 "SAN JUAN BASIN PIT CLOSURES, SAN JUAN BASIN, NEW MEXICO, PIT CLOSURE REPORT". These documents contain the results of pit closure activities at 39 sites which encountered shallow ground water.

The OCD's review of the above referenced documents is addressed below:

A. The pit closure/remediation activities conducted at the sites listed below are **approved**.

1. Apache Federal #4 (Drip pit)	Unit M, Sec. 07, T24N, R05W.
2. Argo #1E (Dehy pit)	Unit N, Sec. 18, T27N, R10W.
3. Burroughs Com #1 (Drip pit)	Unit H, Sec. 36, T27N, R08W.
4. Candelaria Gas Com C#1 (Drip pit)	Unit C, Sec. 27, T29N, R10W.
5. Canyon Largo Unit #298 (Drip pit)	Unit A, Sec. 03, T24N, R06W.
6. Canyon Largo Unit #302 (Drip pit)	Unit J, Sec. 03, T24N, R06W.
7. Canyon Largo Unit #336 (Drip pit)	Unit C, Sec. 24, T25N, R06W.
8. Charley Pah #4 (Drip pit)	Unit K, Sec. 12, T27N, R09W.
9. Cleveland No.6 (Drip pit)	Unit B, Sec. 21, T27N, R09W.
10. Cutler #2 (Drip pit)	Unit A, Sec. 14, T24N, R06W.
11. Federal 6 #32 CH (Drip pit)	Unit G, Sec. 06, T26N, R07W.
12. Federal R#2 (Drip pit)	Unit P, Sec. 15, T27N, R08W.
13. Flora Vista #1 (Dehy pit)	Unit F, Sec. 22, T30N, R12W.
14. Gartner LS #7 (Dehy pit)	Unit K, Sec. 26, T30N, R08W.
15. Grace Pearce #1 (Drip pit)	Unit O, Sec. 22, T29N, R11W.
16. Green Com #1 (Drip pit)	Unit E, Sec. 36, T29N, R09W.
17. Hammond Fed #1 (Drip pit)	Unit L, Sec. 25, T27N, R08W.
18. Hammond Fed #5 (Drip pit)	Unit D, Sec. 25, T27N, R08W.
19. Hammond #7 (Drip pit)	Unit G, Sec. 26, T27N, R08W.
20. Hammond #92 (Drip pit)	Unit O, Sec. 25, T27N, R08W.
21. Howell #3 (Drip pit)	Unit C, Sec. 03, T27N, R08W.
22. Krause WN Federal #1E (Drip pit)	Unit C, Sec. 32, T28N, R11W.
23. Lat 2C-55 Line Drip (Drip pit)	Unit F, Sec. 17, T25N, R07W.
24. Lindrith Unit #23 (Drip pit)	Unit O, Sec. 09, T24N, R03W.

Ms. Sandra Miller  
January 24, 1997  
Page 2

25. Marshall "B" #1J (Drip pit)	Unit O, Sec. 14, T27N, R09W.
26. Ona McGee #1 (Dehy pit)	Unit P, Sec. 04, T30N, R11W.
27. Price #3 (Dehy pit)	Unit A, Sec. 15, T28N, R08W.
28. Sanchez Gas Com C#1 (Drip pit)	Unit A, Sec. 28, T29N, R10W.
29. Valdez #2 (Drip pit)	Unit G, Sec. 24, T29N, R11W.


Please be advised that OCD approval does not relieve EPFS of liability if remaining contaminants are found to pose a future threat to surface water, ground water, human health or the environment. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state or local laws and/or regulations.

- B. Ground waters at the sites listed below are contaminated with petroleum related constituents in excess of New Mexico Water Quality Control Commission ground water standards. At these sites, subsequent closure monitoring was not performed or the extent of ground water contamination at the sites was not been determined. Therefore, approval of these pit closure forms is **denied**. The OCD requests that, as necessary, EPFS investigate the extent of contamination, perform subsequent closure monitoring and/or remediate contaminated ground water pursuant to EPFS's November 29, 1995 ground water investigation/remediation work plan which was approved by the OCD on November 30, 1995.

1. 2C-22 #3 Line Drip (Drip pit)	Unit G, Sec. 13, T24N, R06W.
2. 2C-45 Line Drip (Drip pit)	Unit P, Sec. 13, T25N, R06W.
3. Canyon Largo Unit #304 (Drip pit)	Unit C, Sec. 11, T24N, R06W.
4. Gallegoc Canyon Unit #188E (Dehy)	Unit B, Sec. 30, T29N, R12W.
5. Graham #53 (Dehy pit)	Unit L, Sec. 10, T27N, R08W.
6. K-17 Line Drip (Drip pit)	Unit C, Sec. 26, T27N, R08W.
7. McGrath #1 (Drip pit)	Unit F, Sec. 07, T30N, R11W.
8. Miles Federal #1E (Dehy pit)	Unit N, Sec. 05, T26N, R07W.
9. Trunk D Line Drip (Loop D-8) (Drip)	Unit F, Sec. 20, T28N, R08W.
10. Trujillo Gas Com A#1 (Drip pit)	Unit C, Sec. 28, T29N, R10W.

If you have any questions, please call me at (505) 827-7154.

Sincerely,



William C. Olson  
Hydrogeologist  
Environmental Bureau

xc: OCD Aztec District Office  
Bill Liess, BLM Farmington District Office  
David Deardorff, New Mexico State Land Office  
Charmaine Tso, Navajo Nation EPA  
Kurt Sandoval, Jicarilla Apache EPO