3R - 284

GENERAL CORRESPONDENCE

YEAR(S): 1992

MERIDIAN OIL

December 9, 1992

Denny Foust New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztee, New Mexico 87410



Dear Mr. Foust:

Please find attached the wellsite information we discussed for the pit closures at the Larcher 1 and Calloway 1A. The laboratory sampling locations are indicated on the diagrams.

If you have any questions or wish to discuss this information, contact me at 326-9537.

Sincerely,

Derin Warren

Environmental Representative

Attachment

xc: File: VA

DRWA-ka:wellinfo

ジベラベー

אר אסיי. בפער היו מיים איים אוני

Meridian Oil Inc. PO Box 4289 Farmington NM 87499-4289

<u>Location</u>	
Lease Name, Well No CALLOWRY	# 1A
SEC 27 TWN 312	RNG_11w
Forman NOEL ROGET	Forman Area No. 331 ()
Vulnerable Area Drainage Animas	, R
<u>Measurement</u>	
Date 9/11/92 Time /	345 - 1145
Instrument <u>P/O (oum) - 374 54</u>	SHOUEL POST HOLE DIEGER
Calibration Date 9/11/92 CoS3) -TIME)
Measured Sample Condition ವ೩೪೦ ರಜ. ನಡಿ	IN- BLACK WELL SORTED MOIST.
PID Hydrocarbon Concentrations in ppm $\frac{18}{V_{E}}$	362(2 FT) 1558(3 FT) 1258(51/2 FT).
	equest only, composite from completed excavation)
CALLOWAY 1A	equest only, composite from completed excavation
Site Conditio_s	
Liquids in pit (V)	Visible hydrocarbor's oil surface (Y) PRODUCT (ASSUMED OIL)
Pit fenced (Y) retted ()	Pit in use () Dehr () Separate ()

Scale 20 FT. | 12.

PIT WESTION: 10 FT. NORTH, 70 FT. WEST OF WELL HEAD.

LABORATORY SAMPLE

TO WELL

HEAD

PIT AREA

(5 FT. DEPRESSION)

TANK


FENCE

1Pive:

PID Measurement for Unlined Pit Closure Assessment Field Screening

Meridian Oil Inc. PO Box 4289 Farmington NM 87499-4289

Location	7
Lease Name, Well No LARCHER #1	1408001190
SEC 7 (K) TWN 310	
Forman NOEL ROBERS	Forman Area No. <u>उउर ८५</u>)
Vulnerable Area Drainage Arimas	R ·
Measure t	
Date 8/26/9 Z Time 08	50 - 0955
Instrument PID (gum) 37454,	L'AND ANGER
Calibration Date 3/25/92 (1235-	TIME)
Measu ad Sample Condition OIYz FT. (0910)	1 1/2 FT (0435), SONDICIAY MUIET
GRAY STRONG ODOR ON BOTH	TAMPLES.
PID Hydrocarbon Concentrations in ppm	1781 (2) 1444
Analyst (Print) NELSON VE	LEZ
Laboratory Sample No (special re-	quest only, composite from completed excavation)
Site Conditions	
Liquids in pit (사)	Visible hydrocarbon : on su ্ e (১)
Pit fenced (Y) netted ()	Pit in use () Dehy (Y) Separator ()



River 1/2 mile

NOTE: TWO DIT WENTIONS FOR THE SAME SEPARATOR WIT LOCATION OF ARMINE IN. FROM GIOLING SWEFACE (GAPPLOX)

MERIDIAN OIL

OIL CONSERS. IN DIVISION RECE VED

'92 NO : 20 AM 9 47

November 17, 1992

Denny Faust New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

Dear Mr. Faust:

Earthen production pits at the Meridian Calloway #1A and Larcher #1 have been closed following verbal approval from Roger Anderson, NMOCD, Santa Fe. The pits were closed September 15 following the excavation of hydrocarbon contaminated soil to the greatest extent possible with a standard backhoe. The excavation followed continuous on site measurement of volatile hydrocarbons with a Thermo Scientific PID instrument. The contaminated soil was removed to the Envirotech commercial landfarm. Ground water was not discovered during the excavation.

Soil samples were collected from the pits at the junction of the sidewall and bottom. At the request of Roger Anderson, one sample was collected from each pit at the point of highest known contamination and analyzed by method 418.1 for TPH. Results of the analysis are attached.

If you have any questions or would like to discuss this information, call me at (505) 326-9537.

Sincerely,

Derin R. Warren

Environmental Representative


XC:

R. Anderson -- NMOCD, Santa Fe

Nocl Rogers

VA File

DRW/vka:soilsmpl



5796 US Highway 64-3014 • Farmington, New Mexico 87401 Phone: (505) 632-0615 • Fax: (505) 632-1865

EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	Meridi Oil	Project #:	91364
Sample ID:	Corner <i>i</i> Pit	Date Reported:	10-28-92
Laboratory Number:	3600	Date Sampled:	09-15-92
Sample Matrix:	Soil	Date Received:	10-26-92
Preservative:	Cool	Date Analyzed:	10-27-92
Condition:	Cool & Intact	Analysis Needed:	TPH

Parameter	Concentration (mg/kg)	Det. Limit (mg/kg)
Total Petroleum Hydrocarbons	686	5.0

Method:

Method 418.1, Petroleum Hydrocarbons, Total

Recoverable, Chemical Analysis of Water and

Waste, USEPA Storet No.4551, 1978


ND - Parameter not detected at the stated detection limit.

Comments: Callov

Calloway #1-A

Analyst.

Review



5796 US Highway 64-3014 • Farmington, New Mexico 87401 Phone: (505) 632-0615 • Fax: (505) 632-1865

EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client: Meridian Oil Project #: 91364 Sample ID: SW Pit/NW Corner Date Reported: 10-28-92 Date Sampled: Laboratory Number: 3601 09-15-92 Sample Matrix: Date Received: 10-26-92 Soil Preservative: Cool Date Analyzed: 10-27-92 Condition: Analysis Needed: TPH Cool & Intact

Parameter	Concentration (mg/kg)	Det. Limit (mg/kg)
Total Petroleum Hydrocarbons	24,800	25.0

Method:

Method 418.1, Petroleum Hydrocarbons, Total

Recoverable, Chemical Analysis of Water and

Waste, USEPA Storet No.4551, 1978

ND - Parameter not detected at the stated detection limit.

Comments:

Larcher #1


Analyst

Partieu

5796 U.S. HIGHWAY 64-3014 FARMINGTON, NEW MEXICO 87401 PHONE: (505) 632-0615

QUALITY ASSURANCE/QUALITY CONTROL

DOCUMENTATION



5796 US Highway 64-3014 • Farmington, New Mexico 87401 Phone: (505) 632-0615 • Fax: (505) 632-1865

EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client: Project #: NA NA Sample ID: Laboratory Blank Date Reported: 10-28-92 Date Sampled: Laboratory Number: TPLB1027 NA Sample Matrix: Soil Date Received: NA Preservative: NA Date Analyzed: 10-27-92 Condition: NA Analysis Needed: TPH

Parameter	Concentration (mg/kg)	Det. Limit (mg/kg)
Total Petroleum Hydrocarbons	ND	5.0

Method:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water and

Waste, USEPA Storet No.4551, 1978

ND - Parameter not detected at the stated detection limit.

Comments:

Analyst

Review

α
Ö
S
Щ
E
>
0
-
SUS
Ξ
U
9
0
_
=
≤
共
O

			נ	CHAIN OF COSTODY RECORD	טמו הבכטתו		
Client/Project Name が死んりかめ Oi() ز٥	41364	91364 Project Location C ALCOWAY#/- LARCHER #	1#/-M	ANALYSIS/PARAMETERS	3AMETERS	
Sampler: (Signature)			Chain of Custody Tape No.	No.		č	Remarks
DERIN WARREN		326-5537			steni	\ C-	11
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. Conta	Kush	Man H
CALLOWAY#1-A	6-12-6	9-15-92 10:304	3600	2017	7	N. 8	N.W CORNER of P.7
1# 23HUUH7	9-15-92	9-15-92 11:00A.	3601	Soil	7	N.W.Con	N.W Corner DPJ
Relinquished by: (Signature)				Date Time	Received by: (Signature)		Date Time
DERIN WARREN	-	by mon! You		192462 1125	Lucla touch	10.	10.26.42 11.25
Relinquished by: (Signature)					Received by: (Signature)		
Relinquished by: (Signature)					Received by: (Signature)		

ENVIROTECH INC. 5796 U.S. Highway 64-3014 Farmington, New Mexico 87401 (505) 632-0615

san juan repro Form 578-81



STATE OF NEW MEXICO

OIL CONSERV-

STATE OF NEW MEXICO OIL CONSERVED

ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT 13

OIL CONSERVATION DIVISION, 93 JAN 11 AZTEC DISTRICT OFFICE

BRUCE KING GOVERNOR

ANITA LOCKWOOD CABINET SECRETARY

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

Certified Mail Receipt #P 988 786 241

January 7, 1992

Meridian Oil Inc. Attn. Derin R. Warren P. O. Box 4289 Farmington, NM 87499-4289

RE: Pit remediation at the Meridian Calloway #1A and Larcher #1

Dear Mr. Warren:

The Oil Conservation Division District III office has determined there is insufficient data available to approve the Meridian pit closures at the Calloway #1A, O-27-31N-11W and the Larcher #1, K-7-31N-10W. The OCD needs evaluation of the impact of Total Petroleum Hydrocarbons left in place. I suggest you review the ranking criteria and risk analysis outlined in the Draft OCD Surface Impoundment Closure Guidelines dated 12/21/92. The volume of contaminated material is a significant factor in risk analysis. Down dip auger testing with PID screening is one option which should indicate the volume of contamination at these locations. At the Larcher #1 more than one core hole may be needed and depth to groundwater may need to be determined because a Total Petroleum Hydrocarbon reading of near 25,000 ppm may indicate persistent BTEX contamination near the water table within the river valley.

Meridian Oil Inc. has until February 15, 1993, to respond with an outline for further remediation at these locations and provide a date for completion of these activities. The OCD District III office is to be notified twenty-four hours before further remedial activity is initiated.

If you have questions please feel free to call this office.

Yours truly,

Denny G. Foust

Environmental Geologist

XC: OCD Environmental Bureau

Environmental File

DGF File