

<b>Location:</b>	<b>Remuda South 25 State 126H</b>	
<b>Spill Date:</b>	<b>10/25/2019</b>	
<b>Approximate Area =</b>	<b>2980.00</b>	<b>sq. ft.</b>
<b>Average Saturation (or depth) of spill =</b>	<b>0.75</b>	<b>inches</b>

<b>Average Porosity Factor =</b>	<b>0.03</b>	
----------------------------------	-------------	--

<b>TOTAL VOLUME OF LEAK</b>		
<b>Total Produced Water =</b>	<b>5.00</b>	<b>bbls</b>

<b>VOLUME RECOVERED</b>		
<b>Total Produced Water =</b>	<b>4.00</b>	<b>bbls</b>

NRM2000237294